

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005412/TVY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00159432102
Claimant Vehicle No :	GBH3318Z	Insured Vehicle No :	SMM3381H
Date of Loss:	27/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203826/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH3318Z	Engine No:	R06A2144452
Make & Model:	SUZUKI EVERY, 658cc GA (A)	Chassis No:	DA17V821267
Reg. Date:	26/04/2018 (Man. Year: 2017)	Odometer:	54742 km
Colour:	Black		
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	155 R12	Rear Tyre Size:	155 R12
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,316.38	2,968.56	6,347.82	68.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,580.00	2,670.00	62.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,566.38	4,548.56	9,017.82	66.47
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	13,566.38	3,600.00	9,966.38	73.46
+ GST 7.00/7.00% (S\$)	949.65	252.00	697.65	73.46
Nett Amount (S\$)	14,516.03	3,852.00	10,664.03	73.46

INSPECTION

Date of Assignment:	15/09/2022	
Date Inspected:	07/06/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Sep 2022)	
Parts:	N/A	SUZUKI EVERY 658cc GA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH3318Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	594.00 FL	*511.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	33.40 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Cracked	33.40 FL	*33.40 FL
4	1		*REAR BUMPER NUMBER PLATE LAMP	Cracked	35.80 FL	*35.80 FL
5	1		*REAR BUMPER NUMBER PLATE LAMP BRACKET	Not Necessary	26.70 FL	*- FL
6	1		*REAR BUMPER TAILLAMP ASSEMBLY RH	Cracked	98.40 FL	*98.40 FL
7	1		*REAR BUMPER TAILLAMP ASSEMBLY LH	Cracked	98.40 FL	*98.40 FL
8	1		*REAR TAILGATE	Bent	986.10 FL	*899.00 FL
9	1		*REAR TAILGATE LOCK ASSEMBLY	Bent	178.30 FL	*150.00 FL
10	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	35.00 FL	*- FL
11	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	144.90 FL	*- FL
12	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	78.40 FL	*- FL
13	1		*REAR TAILGATE EMBLEM	Necessary	35.00 FL	*35.00 FL
14	1		*REAR TAILGATE EVERY STICKER EMBLEM	Necessary	40.00 FL	*40.00 FL
15	1		*REAR TAILGATE STICKER EMBLEM	Necessary	35.00 FL	*35.00 FL
16	1		*REAR END PANEL	Bent	654.90 FL	*480.00 FL
17	1		*REAR END PANEL AIR DUCT RH	Not Necessary	42.10 FL	*- FL
18	1		*REAR END PANEL AIR DUCT LH	Not Necessary	42.10 FL	*- FL
19	1		*REAR FLOOR PANEL	Not Necessary	1,372.00 FL	*- FL
20	1		*REAR FLOOR PANEL INSULATOR RH	Not Necessary	143.50 FL	*- FL
21	1		*REAR FLOOR PANEL INSULATOR LH	Not Necessary	143.50 FL	*- FL
22	1		*REAR FENDER RH	Not Necessary	873.60 FL	*- FL
23	1		*REAR FENDER LH	Not Necessary	873.60 FL	*- FL
24	1		*REAR FENDER INNER TRIM RH	Not Necessary	101.00 FL	*- FL
25	1		*REAR FENDER INNER TRIM LH	Not Necessary	101.00 FL	*- FL
26	1		*REAR FENDER INNER SHIELD RH	Not Necessary	67.40 FL	*- FL
27	1		*REAR FENDER INNER SHIELD LH	Not Necessary	67.40 FL	*- FL
28	1		*REAR EXHAUST PIPE	Bent	452.90 FL	*452.90 FL
29	1		*REAR EXHAUST GASKET	Not Necessary	48.00 FL	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	29.80 FL	*- FL
31	1		*SPARE TYRE CARRIER	Not Necessary	377.20 FL	*- FL
32	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
36	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
37	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*40.00 FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
40	1		*REAR FENDER SEALANT	Not Necessary	300.00 FS	*- FS
41	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	150.00 FS	*50.00 FS
42	1		*SET REAR TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*30.00 FS
44	1		*REAR TAILGATE 5 PAX STICKER	Necessary	30.00 FS	*30.00 FS
45	1		*REAR TAILGATE LALAMOVE STICKER	Necessary	500.00 FS	*150.00 FS
46	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
			F=Franchise part. S=SpcNett. L=ListItemDisc.			
					Sub Total (\$)	10,492.80
					3,398.90	
					- List Item Discount on L Items 15.00/15.00% (\$)	1,176.42
						430.34
					Total Parts (\$)	9,316.38
						2,968.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,200.00	600.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
5	TO TRANSFER TAILGATE MECHANISM	New	150.00	60.00
6	TO REMOVE & REFIX REAR BUMPER EVERSE CAMERA	New	150.00	0.00
7	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	30.00
8	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	60.00
9	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	30.00
10	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	50.00
11	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
12	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			4,250.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >