

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005414/UQY3N2**Date:** 15/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00062562101
Claimant Vehicle No :	SMU8325X	Insured Vehicle No :	GBC767G
Date of Loss:	31/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203847/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8325X	Engine No:	G4FGLU122515
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMLU100250
Reg. Date:	31/08/2020 (Man. Year: 2020)	Odometer:	22530 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,080.80	2,507.55	3,573.25	58.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,400.00	1,270.00	47.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,750.80	3,907.55	4,843.25	55.35
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	8,750.80	3,100.00	5,650.80	64.57
+ GST 7.00/7.00% (\$\$)	612.56	217.00	395.56	64.57
Nett Amount (\$\$)	9,363.36	3,317.00	6,046.36	64.57

INSPECTION

Date of Assignment:	11/06/2022	
Date Inspected:	09/06/2022 Inspected At:	BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840 REPAIRER: FALCON-AIR AUTO SERVICES PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU8325X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR FENDER	Repair	2,701.51 FL	*- FL
2	1		*O/S TAILLAMP	Not Necessary	784.23 FL	*- FL
3	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	151.32 FL	*- FL
4	1		*O/S REAR DOOR	Dented/Bent	1,846.98 FL	*1,846.98 FL
5	1		*O/S REAR DOOR RUBBER	Necessary	265.31 FL	*265.31 FL
6	1		*O/S REAR DOOR OUTER HANDLE	Not Necessary	285.75 FL	*- FL
7	1		*SET O/S REAR DOOR BLACK STICKER	Necessary	84.65 FL	*84.65 FL
8	1		*SET O/S REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
9	1		*SET O/S REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
10	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	45.00 FS	*- FS
11	1		*O/S REAR DOOR BODY SEALANT	Necessary	80.00 FS	*50.00 FS
12	1		*SET O/S REAR DOOR TRIM BOARD CLIP	Necessary	50.00 FS	*50.00 FS
13	1		*O/S REAR RIM	Cut	650.00 FS	*650.00 FS
14	1		*TYRE	Serviceable	180.00 FS	*- FS
15	1		*SET O/S REAR DOOR INNER PLASTIC FILM AND SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,304.75	2,946.94
- List Item Discount on L Items 20.00/20.00% (S\$)	1,223.95	439.39
Total Parts (S\$)	6,080.80	2,507.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	ANTI-RUST	New	100.00	30.00
3	TO APPLY BODY SEALANT ON BODY JOINTS	New	100.00	0.00
4	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
5	TRANSFER DOOR PARTS	New	100.00	60.00
6	TRANSFER REAR WINDSCREEN GLASS	New	120.00	0.00
7	TO REPROGRAM AND RESET DOOR MEMORY	New	280.00	50.00
8	LABOUR/PANEL BEATING	New	900.00	580.00
9	SPRAY PAINTING 1)-RR BUMPER 2)-O/S RR FENDER 3)-O/S RR DOOR 4)-O/S ROCKER PANEL	New	900.00	600.00
Gross Labour Cost (\$\$)			2,670.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >