

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005417/KNY3Q2**Date:** 04/01/2023**REFERENCE**

| | | | |
|------------------------------|---|-----------------------------|----------------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00120592100 |
| Claimant Vehicle No : | SMK964G | Insured Vehicle No : | GBC2848T |
| Date of Loss: | 02/06/2022 | Nature of Claim: TP | Claim No: SNM22D203975/C02/TANKW |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SMK964G | | |
| Make & Model: | HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) | Engine No: | L15B31000080 |
| Reg. Date: | 15/10/2014 (Man. Year: 2014) | Chassis No: | JHMGK5850FX201252 |
| Colour: | Metallic Yellow | Odometer: | 87870 km |
| Engine Capacity: | 1498 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/55 R16 | Rear Tyre Size: | 185/55 R16 |
| Front Left Side: | Yokohama 7 mm | Rear Left Side: | Yokohama 4 mm |
| Front Right Side: | Yokohama 7 mm | Rear Right Side: | Yokohama 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,569.00 | 2,229.00 | 340.00 | 13.23 |
| Miscellaneous Items | 160.00 | 120.00 | 40.00 | 25.00 |
| Labour | 2,810.00 | 2,460.00 | 350.00 | 12.46 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,539.00 | 4,809.00 | 730.00 | 13.18 |
| Approved Total (Overridden) (S\$) | | 3,800.00 | | |
| (S\$) | 5,539.00 | 3,800.00 | 1,739.00 | 31.40 |
| + GST 7.00/7.00% (S\$) | 387.73 | 266.00 | 121.73 | 31.40 |
| Nett Amount (S\$) | 5,926.73 | 4,066.00 | 1,860.73 | 31.40 |

INSPECTION

| | | |
|-----------------------------|------------------------------|--|
| Date of Assignment: | 07/06/2022 Present Location: | Cheng Hoe Motor Pte Ltd (Yishun) 10 ANG MO KIO IND PARK 2A |
| Date Inspected: | 20/06/2022 Inspected At: | #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047 Repairer:Cheng Hoe Motor Pte Ltd (Yishun) |
| Estimated Period of Repair: | 8.0 days | |

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 04 Jan 2023) |
| Parts: | 144 | HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMK964G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|--------------------------------------|-------------|------------|-------------------|
| 1 | 1 | | *1 PC REAR BUMPER | Mtg Cracked | 220.00 F | *220.00 F |
| 2 | 1 | | *1 PC REAR BUMPR SIDE RETAINER LH | Cracked | 14.00 F | *14.00 F |
| 3 | 1 | | *1 PC REAR BUMPER INNER SHIELD LH | Cracked | 60.00 F | *60.00 F |
| 4 | 1 | | *1 PC REAR LH FENDER | Bent | 460.00 F | *460.00 F |
| 5 | 1 | | *1 PC REAR LH TRIANGE GLASS MOULDING | Necessary | 30.00 F | *30.00 F |
| 6 | 1 | | *1 PC REAR LH DOOR | Bent | 470.00 F | *470.00 F |
| 7 | 1 | | *1 PC REAR LH DOOR FRAME STICKER | Necessary | 15.00 F | *15.00 F |
| 8 | 1 | | *1 PC FRT LH DOOR | Bent | 510.00 F | *510.00 F |
| 9 | 1 | | *1 PC FR TLH DOOR FRAME STICKER | Necessary | 30.00 F | *30.00 F |
| 10 | 1 | | *1 PC FRT LH OUTER HANDLE | Dented | 130.00 F | *130.00 F |
| 11 | 1 | | *1 PC FRT LH DOOR GLASS | Cut | 290.00 F | *290.00 F |
| 12 | 1 | | *1 PC LH SIDE SKIRT | Serviceable | 340.00 F | *- F |
| Total Parts (S\$) | | | | | | 2,569.00 2,229.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|---|---------------|---------------|
| Miscellaneous Items | | | | |
| 1 | 1 | 1 PC FRT LH DOOR GLASS TINTED FILM (Necessary) | 120.00 | 80.00 |
| 2 | 1 | 1 PC RER LH FENDER GLASS SEALANT (Necessary) | 40.00 | 40.00 |
| Sub Total (\$\$) | | | 160.00 | 120.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | 1) TO REMVOE AND REFIX REAR BUMPER & ATTAHCMENTS, TAILLAMPS, LH SIDE SKIRT, BOTH LH DOORS & ATTACHMENTS; CUT, WELD AND RENEW REAR LH FENDER, KNOCK AND REPAIR REAR H DOOR PILLAR AND RE-ALIGN TO SAMES | New | 1,100.00 | 1,000.00 |
| 2 | 2) TO PUTTY AND RESPRAY ON BOTH LH DOORS & PILLAR, SIDE MIRROR, LH SIDE SKIRT, REAR BUMPER, REAR LH FENDER AND ALL AFFECTED AREAS | New | 1,300.00 | 1,100.00 |
| 3 | 3) TO REMVOE AND REFIX REAR LH FENDER TRIANGLE GLASS | New | 50.00 | 50.00 |
| 4 | 4) TO REMVOE AND REFIX BOTH LH DOOR GLASS AND RESET CENTRAL LOCKING | New | 120.00 | 120.00 |
| 5 | 5) TO REMOVE AND REFIX REAT SEAT, CARPET TO FACILITATE ON REPAIRS | New | 120.00 | 100.00 |
| 6 | 6) TO RUSTPROOFING | New | 120.00 | 90.00 |
| Gross Labour Cost (\$\$) | | | 2,810.00 | 2,460.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >