

ASS. REC. BY:

REF:

CT2/ 220054201ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP 1562L

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy CHR

c.c

1797

Colour

M.P. white

A/C:

Insured / Std / NI / NA

Sp. Reading

83775

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZYX10

200835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/5/22

D.O.I.

6/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/6/21 Rm @ 1300L Carbn

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLP1562L

Not Authorized
Putnam Bkpram
3 days

11 Sing @ 1300/-

Spare Parts

No.	Qty	List Items			
1	1	Rear bumper top	\$	472.70	✓
2	1	Rear bumper bottom	\$	396.30	✓
3	1	Rear bumper side reflector cover	\$	193.20	X
4	2	Rear bumper side reflector	\$	126.80	X
5	2	Rear bumper side retainer	\$	217.00	X
6	1	Rear bumper inner reinforcement	\$	353.10	X
7	1	Rear tailgate	\$	1,082.50	X
8	1	Rear tailgate centre "TOYOTA" logo	\$	65.90	X
9	1	Rear tailgate RH "HYBRID SYNERGY DRIVE" emblem	\$	50.80	✓
10	1	Rear tailgate LH "CHR" emblem	\$	48.30	X
			\$	3,006.60	
			Less 25%	\$ 751.65	
			Total :	\$ 2,254.95	

Special Nett Items

11	1 set	Rear windscreen sealant	\$	50.00	X
12	1 set	Reverse sensors	\$	300.00	2000m
			Total :	\$ 350.00	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	800.00	300
2	To putty and spray Spray Paintings charges.	\$	800.00	440
3	To check wirings and lightings.	\$	50.00	15
4	To remove, refit reverses sensors.	\$	80.00	50
5	To remove, refit rear windscreen glass.	\$	na 140.00	X
6	To remove, refit rear tailgate fittings.	\$	na 80.00	X
7	To remove, refit rear upholstery and attachments.	\$	na 120.00	X
8	To apply anti rust treatment	\$	na 80.00	X
Total :		\$	2,150.00	

Total Parts and Labour : \$ 4,754.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: