



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 573G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S TAIL LAMP ASSY	BROKEN	436.70	436.70
2	O/S TAIL LAMP CLIPS STOPPER @\$5.90	NOT NECESSARY	11.80	-
1	REAR BUMPER	DEFORMED	811.90	811.90
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR BUMPER O/S SIDE RETAINER	BENT	20.10	20.10
1	SET REAR BUMPER REVERSE SENSOR	SHORTED	287.90	287.90
1	TAIL GATE DOOR 'FREED' EMBLEM	NECESSARY	47.90	47.90
1	TAIL GATE DOOR 'H' EMBLEM	NECESSARY	30.60	30.60
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,234.50	-
8	REAR O/S FENDER INNER SHIELD CLIPS @\$5.90	NOT NECESSARY	47.20	-
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	1,118.90	-
15	REAR O/S DOOR INNER TRIM BOARD CLIPS @\$5.90	NOT NECESSARY	88.50	-
1	FRONT O/S DOOR	NOT NECESSARY	1,985.80	-
15	FRONT O/S DOOR INNER TRIM BOARD CLIPS @\$5.90	NOT NECESSARY	88.50	-
1	FRONT O/S FENDER	NOT NECESSARY	600.00	-
	LESS 20% DISCOUNT		-1,369.86	-334.82
			5,479.44	1,339.28
LABOUR				
	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM.		60.00	20.00
	TO REMOVE & REFIX REAR O/S FENDER INNER SHIELD, REAR O/S DOOR & FRONT O/S DOOR INNER TRIM BOARD COVER, GLASS, WEATHERSTRIP & NECESSARY PARTS. }		260.00	80.00
	TO REMOVE & REFIX CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, SPARE TYRE & NECESSARY PARTS FOR ENABLE REPAIR. }		120.00	-
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	150.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR O/S FENDER AND REAR O/S DOOR.		1,650.00	520.00

Report Ref No. CS/SMO22005425/Uny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,900.00	800.00
			4,140.00	1,420.00
GRAND TOTAL			9,619.44	2,759.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/SMO22005425/Uny3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.