

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 2021 – 94 Date: 10th Jun 2022

Our Ref: CS1/SCD22005427/Kqy3e2

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4 Singapore 408827

Attn: Ralf Tay

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 7708K INSURED VEHICLE: QX 1222S ACCIDENT DATE: 16/10/2021

We thank you for your instruction on 07/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 7708K from M/s Comfortdelgro Engineering Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SHC 7708K.
- c) Colour damaged vehicle photographs of SHC 7708K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SHC 7708K

Make & Model : Hyundai AE Ioniq HEV FL 1.6 DCT

Year of Registration : 2019
Chassis Number : KMF

Chassis Number : KMHC851CVLU180858

Engine Capacity : 1580 cc



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

2.	Our finding is that the repair cost of \$1,021.00 (before GST) quoted by M/s Comfortdelgro
	Engineering Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about <u>2 (Two)</u> working days to complete.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7708K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING	SNAPPED	451.25	451.25
10	REAR BUMPER CLIPS	REUSE	22.00	-
	LESS 20% DISCOUNT		-186.53	-90.25
			746.12	361.00
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	REUSE	180.00	-
			180.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGES.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	60.00
			820.00	660.00
	GRAND TOTAL		1,746.12	1,021.00

RECOMMENDED COST OF REPAIRS		1,021.00

Report Ref No. CS1/SCD22005427/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser