

VICOM LTD 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

www.vicom.com.sg Company Registration No: 198100320K

TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD #205 Braddell Road Blk C Ext 1 3rd Level Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SHC7708K

/ CIDENT DATE : 16/10/2021

CLAIM No.

: 305491109

INSURED VEH.No: QX1222S

GST REG No. : M9-0000652-A

CUSTOMER ID : VACC0013

INVOICE No. : LY013659


INVOICE DATE: 01/11/2021

PAYMENT TERM: 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE(SG\$) AM	AMOUNT (SG\$)	
Photographs	6	1.00	\$	6.00	
Transportation	1	50.00	\$	50.00	
VAC Assessment Fee	1	125.00	\$	125.00	

REMARKS	GROSS	AMOUNT \$	181.00
CCPL	GST @	7% \$	12.67
	INVOIC	E AMOUNT \$	193.67

This is a computer generated TAX INVOICE No signature required





VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

www.vicom.com.sg Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No.

: 570704

Claim No.

: 305491109

Accident Date

: 16/10/2021

Claim Type : THIRD PARTY

Assignment Date

: 19/10/2021

Policy No.

Survey Date

: 19/10/2021

Finalised Dt .:

Survey Report Date : 30/10/2021

VEHICLE PARTICULARS

Vehicle No.

: SHC7708K

Chassis No. : KMHC851CVLU180858

Registration Date : 22/10/2019

Engine No. : OBSCURED

: HYUNDAI

Engine Cap. : 1580 CC

Model

: IONIQ (G3)

Transmission: AUTO

Colour

: YELLOW

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake

: SERVICEABLE

Steering

: SERVICEABLE

Hand Brake

: SERVICEABLE

Modification: NONE

Mileage

TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH	195/60R16	WESTLAKE	6
FRONT LH	195/60R16	WESTLAKE	6
REAR RH	195/60R16	WESTLAKE	6
REAR LH	195/60R16	WESTLAKE	6

SURVEY CONDUCTED AT

59 Loyang Drive Singapore 508969

REMARKS

[1] Workshop Estimate : S\$ 1,746.12 [2] Our Adjustment S\$ 1,021.00

[3] Repair Period

2 days

[4] We have not authorised repairs. This survey was carried out on without prejudice basis.

VICOM LTD SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition		Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Repair		459.40	0.00
2	1	Rear Bumper Centre Moulding	Snapped		451.25	451.25
3	10	Rear Bumper Clips	Reuse		22.00	0.00
			Subtotal	:	932.65	451.25
	Less 20 %	Less 20 %			186.53	90.25
			TOTAL	:	746.12	361.00
		SPECIAL NETT ITEM				
1_	1	Reverse Sensor	Reuse		180.00	0.00
()			TOTAL	:	180.00	0.00
		TOTAL FOR SPARE PARTS		:	926.12	361.00

VICOM LTD SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description			Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges			400.00	350.00
2	Spray painting charges			300.00	250.00
3	Remove/ refix reverse sensor			120.00	60.00
	1	OTAL FOR LABOUR AND SPRAY PAINTING	:	820.00	660.00

Summary

Description		Workshop Estimate (S\$)	VAC Adjstment (S\$)
TOTAL FOR SPARE PARTS	:	926.12	361.00
TOTAL FOR LABOUR AND SPRAY PAINTING	:	820.00	660.00
TOTAL REPAIR COST	:	1746.12	1021.00

. VICOM LTD SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$1,746.12. We adjusted it to S\$1,021.00 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,021.00.

The repairs would require a period of 2 working days.

Kamarudin Abdul Kadir for VICOM Ltd