

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005431/AVY3Q2**Date:** 07/10/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00124662200

Claimant Vehicle No : SKU2278L **Insured Vehicle No :** SLJ1476J

Date of Loss: 05/06/2022 Nature of Claim: TP Claim No: SNM22D204103/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU2278L**

Make & Model: BMW 318I, 1.8 (A) Engine No: B878I861N46B20BZ

Reg. Date: 28/12/2010 (Man. Year: 2010) Chassis No: WBAPF72050A794276

Colour: Black Odometer: 191768 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35 R18 Rear Tyre Size: 255/35 R18

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,768.72	3,901.59	5,867.13	60.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	1,370.00	3,510.00	71.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,648.72	5,271.59	9,377.13	64.01
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	14,648.72	4,200.00	10,448.72	71.33

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 07/06/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts: 143	BMW 318I 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKU2278L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,069.10 FL	*1,069.10 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	190.00 FL	*95.00 FL
3	1		*REAR BUMPER SIDE BRACKET	Not Necessary	126.70 FL	*- FL
4	1		*REAR WINDSCREEN MOULDING TOP	Not Necessary	95.00 FL	*- FL
5	2		*REAR WINDSCREEN MOULDING SIDE	Not Necessary	172.00 FL	*- FL
6	1		*REAR FENDER LH	Repair	1,426.00 FL	*- FL
7	1		*REAR FENDER COWLING LH	Not Necessary	429.65 FL	*- FL
8	1		*REAR WHEEL RIM LH	Cut	1,064.00 FS	*650.00 FS
9	1		*REAR ABS SENSOR LH	Not Necessary	327.75 FL	*- FL
10	1		*REAR LOWER ARM LH	Bent	979.65 FL	*395.00 FL
11	1		*REAR UPPER ARM LH	Bent	784.55 FL	*304.00 FL
12	1		*REAR KNUCKLE ARM LH	Damaged	1,248.70 FL	*1,009.00 FL
13	1		*REAR SHOCK ABSORBER LH	Not Necessary	694.45 FL	*- FL
14	1		*REAR LINKAGE LH	Not Necessary	195.00 FL	*- FL
15	1		*REAR WHEEL HUP LH	Damaged	298.35 FL	*298.35 FL
16	1		*REAR WHEEL HUP BEARING LH	Damaged	199.65 FL	*199.65 FL
17	1		*SET REAR BUMPER LH	Necessary	100.00 FS	*50.00 FS
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
19	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
20	1		*SET REAR FENDER COWLING CLIP LH	Not Necessary	80.00 FS	*- FS
21	1		*REAR WHEEL TYRE LH	Not Necessary	480.00 FS	*- FS
22	1		*BRAKE OIL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,180.55	4,070.10
- List Item Discount on L Items 5.00/5.00% (\$\$)	411.83	168.51
Total Parts (\$\$)	9,768.72	3,901.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	500.00
3	TUFF COAT	New	250.00	40.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
5	WIRING CHECK	New	250.00	30.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	160.00	0.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	220.00
9	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	RESET ABS LIGHT	New	350.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
			Gross Labour Cost (\$\$)	4,880.00
				1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >