

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005442/KVY3Q2**Date:** 12/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00003732205

Claimant Vehicle No : GBL5049R **Insured Vehicle No :** CB8487E

Date of Loss: 06/06/2022 Nature of Claim: TP Claim No: SNM22D203995/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL5049R**

Make & Model: NISSAN NV200, 1.6 PETROL (A) Engine No: HR16188911D

Reg. Date: 31/08/2021 (Man. Year: 2021) Chassis No: JN1YAAM20Z0002161

Colour: Metallic Grey Odometer: 11157 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14

Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm

Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,127.00	3,212.00	915.00	22.17
Miscellaneous Items	290.00	290.00	0.00	0.00
Labour	2,010.00	1,780.00	230.00	11.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,427.00	5,282.00	1,145.00	17.82
+ GST 7.00/7.00% (\$\$)	449.89	369.74	80.15	17.82
Nett Amount (\$\$)	6,876.89	5,651.74	1,225.15	17.82

INSPECTION

Date of Assignment: 08/06/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 08/06/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Aug 2022)	
Parts:	N/A	NISSAN NV200 1.6 PETROL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5049R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*1 PC REAR BUMPER	Bent	390.00 F	*390.00 F
2	1	*1 PC REAR BUMPER SPONGE	Cracked	95.00 F	*95.00 F
3	1	*6 PCS REAR BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
4	1	*1 PC TAILGATE	Bent	1,250.00 F	*1,250.00 F
5	1	*1 PC TAILGATE INNER LOCK	Dented	55.00 F	*225.00 F
6	1	*1 PC TAILGATE INNER RUBBER	Distorted / Dented	100.00 F	*100.00 F
7	1	*1 PC TAILGATE LOGO	Necessary	65.00 F	*65.00 F
8	1	*1 PC TAILGATE EMBLEM (NV200)	Necessary	65.00 F	*65.00 F
9	1	*1 PC TAILGATE EMBLEM (VANETTE)	Necessary	65.00 F	*65.00 F
10	1	*1 PC TAILGATE OUTER GARNISH	Cut	195.00 F	*195.00 F
11	1	*1 PC REAR END PANEL (OUTER)	Bent	150.00 F	*150.00 F
12	1	*1 PC REAR END PANEL (INNER)	Bent	490.00 F	*490.00 F
13	1	*1 PC REAR END PANEL INNER TOP GARNISH	Dented	90.00 F	*90.00 F
14	1	*4 PCS REAR END PANEL INNER TOP GARNISH CLIPS @5/PC	Necessary	20.00 F	*20.00 F
15	1	*1 PC REAR FLOOR BOARD	Repair	860.00 F	*- F
Supplementary #1					
16	1	*1 pc tailgate inner lock	Repeated	225.00 F	*- F
Total Parts (S\$)				4,127.00	3,212.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC TAILGATE STICKER - 70KM/H (NECESSARY)	10.00	10.00
2	1	1 SET REVERSE SENSOR (SHORTED)	200.00	200.00
3	1	1 UNIT REAR END PANEL SEALANT (NECESSARY)	40.00	40.00
4	1	1 UNIT REAR WINDSCREEN GLASS SEALANT (NECESSARY)	40.00	40.00
Sub Total (\$\$)			290.00	290.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENT, TAILLAMPS, TAILGATE & ATTACHMENTS, CUT, WELD & RENEW REAR END PANEL OUTER & INNER, REAR FLOORBOARD AND REALIGN THE SAME	New	1,000.00	900.00
3	PUTTY & RESPRAY TAILGATE, REAR END PANEL OUTER & INNER, REAR FLOORBOARD AND ALL AFFECTED AREAS	New	800.00	700.00
4	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (\$\$)			2,010.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >