

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG22005444/UNY3E2

Date: 14/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001450519
Claimant Vehicle No :	GBF5341C	Insured Vehicle No :	SKV1147H
Date of Loss:	06/06/2022	Nature of Claim:	TP
		Claim No:	276194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF5341C	Engine No:	1KD2672648
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Chassis No:	JTFHT02P600212431
Reg. Date:	05/12/2016 (Man. Year: 2016)	Odometer:	172813 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Goform 6 mm	Rear Left Side:	Wonder 6 mm
Front Right Side:	Goform 6 mm	Rear Right Side:	Wonder 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,996.10	1,280.32	3,715.78	74.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,220.00	990.00	44.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,206.10	2,500.32	4,705.78	65.30
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	7,206.10	2,000.00	5,206.10	72.25
+ GST 7.00/7.00% (S\$)	504.43	140.00	364.43	72.25
Nett Amount (S\$)	7,710.53	2,140.00	5,570.53	72.25

INSPECTION

Date of Assignment:	13/06/2022		
Date Inspected:	08/06/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF5341C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR O/S	Dented/Bent	1,866.10 F	*1,545.10 FL
2	1		*REAR FENDER O/S	Repair	1,895.10 F	*- FL
3	1		*REAR WHEEL HUB CAP O/S	Damaged	228.00 F	*162.00 FL
4	1		*REAR WHEEL RIM O/S	Not Necessary	100.00 F	*- FL
5	1		*REAR WHEEL RIM SHAFT O/S	Not Necessary	645.10 F	*- FL
6	1		*REAR SHOCK ABSORBER O/S	Not Necessary	261.80 F	*- FL
					Sub Total (\$\$)	4,996.10 1,707.10
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 426.78
					Total Parts (\$\$)	4,996.10 1,280.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO TRANSFER SLIDING DOOR COMPONENTS	New	80.00	50.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	580.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
7	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	200.00	0.00
Gross Labour Cost (\$\$)			2,210.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >