

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005453/ANCE2**Date:** 07/02/2023**REFERENCE**

Insured/Claimant:	DEBORAH KHOO WEN SHI	Policy No:	2100478645-05	
Date of Loss:	05/06/2022	Nature of Claim:	OD	Claim No: 7288759242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF672L	Engine No:	CHZ102481
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Chassis No:	WAUZZZ8X2GB113544
Reg. Date:	11/08/2016 (Man. Year: 2016)	Odometer:	73659 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R16	Rear Tyre Size:	215/45 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,921.00	3,196.00	12,725.00	79.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,464.00	1,482.00	7,982.00	84.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,385.00	4,678.00	20,707.00	81.57
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	24,785.00	4,078.00	20,707.00	83.55
+ GST 8.00/8.00% (S\$)	1,982.80	326.24	1,656.56	83.55
Nett Amount (S\$)	26,767.80	4,404.24	22,363.56	83.55

INSPECTION

Date of Assignment:	08/06/2022		
Date Inspected:	07/06/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,738.00 FS	*1,390.40 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	259.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Torn	187.00 FS	*149.20 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	452.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
6	1		*LOCK CARRIER	Not Necessary	1,137.00 FS	*- FS
7	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
8	1		*RADIATOR SEAL - LOWER	Not Necessary	29.00 FS	*- FS
9	1		*NOISE INSULATION	Torn	355.00 FS	*284.00 FS
10	1		*UNDERBODY TRIM	Not Necessary	237.00 FS	*- FS
11	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
13	1		*ALUMINIUM RIM	Cut	1,303.00 FS	*1,042.40 FS
14	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
15	1		*SUSPENSION SUBFRAME ASSEMBLY CARRIER	Not Necessary	1,143.00 FS	*- FS
16	1		*TRACK CONTROL ARM - RH	Not Necessary	335.00 FS	*- FS
17	1		*FRONT WHEEL BEARING HOUSING BRAKE CALIPER - RH	Not Necessary	533.00 FS	*- FS
18	1		*SUSPENSION GUIDE JOINT - RH	Not Necessary	126.00 FS	*- FS
19	1		*ANTI-ROLL BAR	Not Necessary	234.00 FS	*- FS
20	1		*COUPLING ROD	Not Necessary	90.00 FS	*- FS
21	1		*FRONT WHEELHUB BEARING	Not Necessary	487.00 FS	*- FS
22	1		*GAS SHOCK ABSORBER	Not Necessary	418.00 FS	*- FS
23	1		*DRIVE SHAFT - RH	Not Necessary	2,161.00 FS	*- FS
24	1		*STEERING GEAR TRACK RODS	Not Necessary	2,824.00 FS	*- FS
25	1		*TRACK ROD	Not Necessary	91.00 FS	*- FS
26	1		*TIE ROD END - RH	Not Necessary	122.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS
28	1		*RHS FRONT TYRE	Punctured	330.00 FS	*330.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **15,921.00** **3,196.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE. VACUUM AND REGAS	New	1,400.00	0.00
3	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	500.00
5	TO RESPRAY FRONT BUMPER	New	900.00	550.00
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	240.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			9,464.00	1,482.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >