



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|--|---|----------------------------------|--|---------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE | | | Ref: CS3/ASM22005454/Evc4 Date: 10/06/2022 Code: ASM | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | | SKW 175C | Veh. Inspected YQ 349J | |
| Policy No. | | | Coverage (\$) 0.00 | |
| Claim No. | | S2M042M8 | Excess (\$) 0.00 | |
| Assign From | | OH VALE | Assign Date 08/06/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | MITSUBISHI CANTER | c.c 2998 | |
| Engine No. | | HIDDEN | Year of Reg. 2019 | |
| Chassis No. | | FEB21EA30052 | Colour WHITE | |
| Odometer | | 140980 KM | Steering IN ORDER | |
| Brakes | | IN ORDER | Modification STANDARD ALLOY RIM | |
| General | | FAIR | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15C | BRIDGESTONE | 4 mm |
| | L/H Front Tyre | 195 R15C | BRIDGESTONE | 4 mm |
| | R/H Rear Tyre | 195 R15C | BRIDGESTONE | 4 mm |
| | L/H Rear Tyre | 195 R15C | BRIDGESTONE | 4 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | |
| 5. General Information | | | | |
| | Accident Date | 27/05/2022 | Inspect Date / Time 09/06/2022 (01:49 PM) | |
| | Survey held at | 4 PENJURU CLOSE SINGAPORE 608574 | | |
| | Repairer | AAK LOGISTICS SERVICES PL | | |
| 5a. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |

Report Ref No. CS3/ASM22005454/Evc4

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.