

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005459/EVY3M4**Date:** 16/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00123222100

Claimant Vehicle No : SLZ6370M **Insured Vehicle No :** YQ4382K

Date of Loss: 02/06/2022 Nature of Claim: TP Claim No: SNM22D203905/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ6370M**

Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A) Engine No: 2ZR0B17967

Reg. Date: 11/05/2018 (Man. Year: 2018) Chassis No: ZVW400028697

Colour: Silver Odometer: 152034 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,781.17	3,702.14	4,079.03	52.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,800.00	200.00	10.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,781.17	5,502.14	4,279.03	43.75
Approved Total (Overridden) (\$\$)		4,400.00		
(\$\$)	9,781.17	4,400.00	5,381.17	55.02
+ GST 7.00/7.00% (\$\$)	684.68	308.00	376.68	55.02
Nett Amount (\$\$)	10,465.85	4,708.00	5,757.85	55.02

INSPECTION

Date of Assignment: 08/06/2022

Date Inspected: 09/06/2022 Inspected At: AF & CARS PTE LTD (HQ)
48 TOH GUAN ROAD EAST, #01-121,
ENTERPRISE HUB
SINGAPORE 608586

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jun 2022)

Parts: 144 TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ6370M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	580.10 FL	*580.10 FL
2	2		*REAR BUMPER SIDE RETAINER L/R	Broken	380.20 FL	*260.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	460.20 FL	*- FL
4	1		*REAR BUMPER NUT & WASHER	Not Necessary	61.90 FL	*- FL
5	1		*REAR TAILLAMP LH	Broken	780.00 FL	*660.00 FL
6	1		*REAR TAILGATE	Dented	1,718.90 FL	*1,177.30 FL
7	2		*REAR TAILGATE HINGES L/R	Not Necessary	460.20 FL	*- FL
8	2		*REAR TAILGATE DAMPER L/R	Not Necessary	760.20 FL	*- FL
9	1		*REAR TAILGATE MECHANISM LOCK	Bent	780.10 FL	*360.00 FL
10	1		*REAR TAILGATE MECHANISM LOCK STRICKER	Not Necessary	61.90 FL	*- FL
11	1		*REAR TAILGATE LOGO EMBLEM	Necessary	61.70 FL	*61.70 FL
12	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	61.29 FL	*61.29 FL
13	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	51.90 FL	*51.90 FL
14	1		*REAR TAILGATE INNER TRIMBOUND (TAILGATE GARNISH)	Broken	890.10 FL	*563.70 FL
15	2		*REAR TAILGATE BUSH L/R	Not Necessary	108.40 FL	*- FL
16	1		*REAR TAILGATE DOOR PULL HANDLE	Not Necessary	91.30 FL	*- FL
17	1		*REAR TAILGATE WEATHER STRIP	Crushed	478.10 FL	*220.00 FL
18	1		*REAR END PANEL (INNER)	Repair	978.10 FL	*- FL
19	1		*REAR END PANEL (OUTER)	Dented	580.20 FL	*580.20 FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	370.10 FL	*- FL
21	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
22	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE	Cut	25.00 FS	*20.00 FS
24	1		*REAR NUMBER PLATE GARNISH	Cut	25.00 FS	*20.00 FS
25	10		*REAR TAILGATE INNER TRIMBOUND CLIPS	Not Necessary	80.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **10,229.89** **4,846.19**
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,448.72 1,144.05

Total Parts (\$\$) **7,781.17** **3,702.14**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX PARKING SENSOR ASSY AND RETIFY FOR PROPER FUNCTIONING	New	80.00	30.00
2	TO DIAGNOSE, REPLACE/OR REPAIR ON THE REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT	New	200.00	50.00
3	TO RESPRAY, PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	800.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE DAMAGED BODYPARTS, REPAIR, ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	800.00
5	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
Gross Labour Cost (\$\$)			2,000.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >