

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22005461/DVY3M4**Date:** 30/06/2022**REFERENCE**

Insured/Claimant: TAN SHI YUN, APRIL Policy No: SP2000790763  
Date of Loss: 06/06/2022 Nature of Claim: OD Claim No: 202222005115JK-SLX1001Y

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLX1001Y**  
Make & Model: HYUNDAI ACCENT, 1.4 (A) Engine No: G4LCJU925489  
Reg. Date: 03/02/2018 (Man. Year: 2018) Chassis No: KMHCU41BTJU414787  
Colour: Red Odometer: 64505 km  
Engine Capacity: 1368 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,628.00	1,298.00	330.00	20.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,100.00	360.00	24.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,088.00</b>	<b>2,398.00</b>	<b>690.00</b>	<b>22.34</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	2,488.00	1,798.00	690.00	27.73
<b>+ GST 7.00/7.00% (S\$)</b>	174.16	125.86	48.30	27.73
<b>Nett Amount (S\$)</b>	<b>2,662.16</b>	<b>1,923.86</b>	<b>738.30</b>	<b>27.73</b>

**INSPECTION**

Date of Assignment: 08/06/2022  
Date Inspected: 08/06/2022 Inspected At: Vins Automotive Group (HQ)  
160 SIN MING DRIVE #03-03  
Singapore 575722  
Estimated Period of Repair: 4.0 days

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2022)
<b>Parts:</b>	144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLX1001Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*RH HEADLAMP</b> (WCP)	Broken	400.00 F	*400.00 F
2	1		<b>*RH HEADLAMP LOWER BRACKET</b> (WCP)	Broken	20.00 F	*20.00 F
3	1		<b>*FRONT BUMPER</b> (WCP)	Cut	280.00 F	*280.00 F
4	1		<b>*FRONT BUMPER RH FOG LAMP</b> (WCP)	Cracked	150.00 F	*150.00 F
5	1		<b>*FRONT BUMPER RH SIDE RETAINER</b> (WCP)	Broken	20.00 F	*20.00 F
6	1		<b>*FRONT BUMPER SPONGE</b> (WCP)	Not Necessary	60.00 F	*- F
7	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Not Necessary	160.00 F	*- F
8	10		<b>*FRONT BUMPER CLIPS @\$2</b> (WCP)	Necessary	20.00 F	*20.00 F
9	1		<b>*WIPER TANK</b> (WCP)	Deformed	50.00 F	*50.00 F
10	1		<b>*FRONT RH FENDER</b> (WCP)	Dented	240.00 F	*240.00 F
11	1		<b>*FRONT RH FENDER INNER SHIELD</b> (WCP)	Serviceable	40.00 F	*- F
12	10		<b>*FRONT RH FENDER INNER SHIELD CLIPS @\$2</b> (WCP)	Not Necessary	20.00 F	*- F
13	1		<b>*FRONT RH FENDER TRIANGLE PLATE (BLACK)</b> (WCP)	Not Necessary	20.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>1,480.00</b>	<b>1,180.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	148.00	118.00
<b>Total Parts (\$\$)</b>	<b>1,628.00</b>	<b>1,298.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR DAMAGE	New	680.00	500.00
2	TO SPRAY PAINTING	New	780.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>1,460.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >