

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22005462/VCY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00083522102

**Claimant Vehicle No :** SMS9822G **Insured Vehicle No :** GBJ7472Z

Date of Loss: 05/06/2022 Nature of Claim: TP Claim No: SNM22D203954/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMS9822G**

Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491031352719

Reg. Date: 21/08/2018 (Man. Year: 2018) Chassis No: WDD2050402R388386

Colour: Blue Odometer: 58551 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,468.10	2,207.10	2,261.00	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	590.00	1,610.00	73.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,668.10</b>	<b>2,797.10</b>	<b>3,871.00</b>	<b>58.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>(S\$)</b>	6,668.10	2,250.00	4,418.10	66.26
<b>+ GST 7.00/7.00% (S\$)</b>	466.77	157.50	309.27	66.26
<b>Nett Amount (S\$)</b>	<b>7,134.87</b>	<b>2,407.50</b>	<b>4,727.37</b>	<b>66.26</b>

**INSPECTION**

Date of Assignment: 08/06/2022

Date Inspected: 09/06/2022 Inspected At: E-Care Auto Services Pte Ltd (HQ)  
Block 51, Ubi Ave 1, #01-29, Paya Ubi Ind Pk  
Singapore 408933

Estimated Period of Repair: 4.0 days

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Sep 2022)

**Parts:** 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMS9822G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,250.00 FL	*1,700.00 FL
2	1		*REAR BUMPER BASIC MOUNTING RH	Necessary	119.00 FL	*119.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	160.00 FL	*- FL
4	1		*REAR TAILLAMP RH (LED)	Serviceable	1,350.00 FL	*- FL
5	1		*REVERSE SENSOR	Cut	680.00 FL	*250.00 FL
6	1		*BUMPER LOWER GARNISH	Scorched	350.00 FL	*350.00 FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,959.00</b>	<b>2,449.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	490.90	241.90
<b>Total Parts (\$\$)</b>	<b>4,468.10</b>	<b>2,207.10</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT TO CUT/WELD REAR PORTION TO REMOVE AND REFIT ABOVE PARTS	New	800.00	300.00
2	TO PUTTY ,RE-SPRAY PAINTING AND POLISH REAR AFFECTED AREAS	New	800.00	200.00
3	TO RUST PROOF AFFECTED REAR AREAS	New	100.00	30.00
4	TO CHECK AND RECTIFY WIRING	New	100.00	30.00
5	TO CONDUCT DISGNOTIC SYSTEM AND CLEAR FAULT CODE	New	300.00	0.00
6	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,200.00</b>	<b>590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >