

**E-CARE AUTO SERVICES PTE LTD**

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Fax: +65 68425377

**Estimate****PAGE : 1/2**

**YEAR :** 2018 **VEHICLE NO :** SMS9822G  
**MODEL :** MERCEDES BENZ C180 AVANTGARDE (R17 LED) **CHASSIS NO :** WDD2050402R388386

Please quote the following items listed.

**Third Party Claims**

S/NO	ITEMS	Qty	Price
1	Rear bumper 1700	1	Rkf \$2,250.00
2	Rear bumper basic mounting RH	1	\$119.00
3	Rear bumper side retainer RH	1	\$160.00
4	Rear taillamp RH (LED)	1	\$1,350.00
5	Reverse sensor	2 x 1	\$680.00
	Bumper lower garnish 350	1	TbC
			\$4,559.00
Discount 10%			\$455.90
<b>TOTAL :</b>			<b>\$4,103.10</b>

S/NO	S/N ITEMS	Qty	Price
1	Rear bumper clips	10	\$50.00
			\$50.00
<b>Parts Total :</b>			<b>\$4,103.10</b>
<b>S/P Item :</b>			<b>\$50.00</b>
<b>TOTAL :</b>			<b>\$4,153.10</b>



E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Fax: +65 68425377

Estimate

PAGE : 2/2

YEAR 2018 VEHICLE NO SMS9822G  
MODEL MERCEDES BENZ C180 AVANTGARDE (R17 LED) CHASSIS NO WDD2050402R388386

S/NO	LABOURS	AMOUNT
1	To straighten and panel beat to cut/weld rear portion to remove and refit above parts.	\$ 800.00
2	To putty, re-spray painting and polish rear affected areas.	\$ 800.00
3	To rust proof affected rear areas.	\$ 100.00
4	To check and rectify wiring.	\$ 100.00
5	To conduct disgnotic system and clear fault code.	\$ 300.00
6	To remove and refit rear reverse sensor.	\$ 100.00

300  
200  
30  
30  
400  
30

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

Thuan @ LKH auto-lom  
8223 5769  
9/6/22 1600  
L/S 3days up

TOTAL : \$ 2,200.00  
PARTS TC : \$ 4,153.10  
GRAND T : \$ 6,353.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: