

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005467/VVY3Q2**Date:** 29/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00153362101

Claimant Vehicle No : SCK7828P **Insured Vehicle No :** GBK8240P

Date of Loss: 04/06/2022 Nature of Claim: TP Claim No: SNM22D203958/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCK7828P**

Make & Model: TOYOTA PREVIA, 2.4 7-seater (A) Engine No: 2AZ4A04063

Reg. Date: 19/06/2015 (Man. Year: 2015) Chassis No: JTEGD54M70A049943

Colour: White Odometer: 0 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,300.83	9,656.87	7,643.96	44.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	1,940.00	3,830.00	66.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,070.83	11,596.87	11,473.96	49.73
Approved Total (Overridden) (S\$)		8,650.00		
(S\$)	23,070.83	8,650.00	14,420.83	62.51
+ GST 7.00/7.00% (S\$)	1,614.96	605.50	1,009.46	62.51
Nett Amount (S\$)	24,685.79	9,255.50	15,430.29	62.51

INSPECTION

Date of Assignment: 26/08/2022

Date Inspected: 10/06/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2022)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCK7828P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	876.57 FL	*876.57 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	92.96 FL	*92.96 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Necessary	92.96 FL	*92.96 FL
4	1		*REAR BUMPER SIDE BRACKET RH	Necessary	92.70 FL	*92.70 FL
5	1		*REAR BUMPER SIDE BRACKET LH	Necessary	92.70 FL	*92.70 FL
6	1		*REAR BUMPER TOWING COVER RH	Serviceable	62.14 FL	*- FL
7	1		*REAR BUMPER TOWING COVER LH	Serviceable	62.14 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Serviceable	176.96 FL	*- FL
9	1		*REAR BUMPER REFLECTOR LH	Cracked	176.96 FL	*176.96 FL
10	1		*REAR BUMPER SPONGE RH	Serviceable	127.41 FL	*- FL
11	1		*REAR BUMPER SPONGE LH	Cut	127.41 FL	*127.41 FL
12	1		*REAR TAILGATE	Dented	1,685.00 FL	*1,685.00 FL
13	1		*REAR TAILGATE EMBLEM	Necessary	75.00 FL	*75.00 FL
14	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	45.00 FL	*45.00 FL
15	1		*REAR TAILGATE PREVIA EMBLEM	Necessary	52.00 FL	*52.00 FL
16	1		*REAR TAILGATE GL EMBLEM	Necessary	45.00 FL	*45.00 FL
17	1		*REAR TAILGATE OUTER CHROME GARNISH	Scratched	253.00 FL	*253.00 FL
18	1		*REAR TAILGATE LOCK ASSEMBLY	Jammed	395.00 FL	*395.00 FL
19	1		*REAR TAILGATE LOCK CATCH	Repair	52.00 FL	*- FL
20	1		*REAR TAILGATE REFLECTOR LAMP RH	Cracked	290.40 FL	*290.40 FL
21	1		*REAR TAILGATE REFLECTOR LAMP LH	Cracked	290.40 FL	*290.40 FL
22	1		*REAR TAILGATE REFLECTOR LAMP CENTRE	Cracked	327.20 FL	*327.20 FL
23	1		*REAR TAILGATE INNER TRIM	Serviceable	486.20 FL	*- FL
24	1		*REAR TAILGATE WEATHERSTRIP	Deformed	365.00 FL	*365.00 FL
25	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	127.80 FL	*127.80 FL
26	1		*REAR TAILGATE ANTENNA SENSOR	Serviceable	197.00 FL	*- FL
27	1		*REAR TAILLAMP ASSEMBLY RH	Cracked	428.10 FL	*428.10 FL
28	1		*REAR TAILLAMP ASSEMBLY LH	Cracked	428.10 FL	*428.10 FL
29	1		*REAR TAILLAMP PANEL RH	Cracked	328.00 FL	*328.00 FL
30	1		*REAR TAILLAMP PANEL LH	Cracked	328.00 FL	*328.00 FL
31	1		*REAR END PANEL	Dented	876.80 FL	*876.80 FL
32	1		*REAR END PANEL TOP GARNISH	Cut	285.00 FL	*285.00 FL
33	1		*REAR END PANEL LOWER GARNISH	Serviceable	194.20 FL	*- FL
34	1		*REAR FENDER RH	Serviceable	1,280.70 FL	*- FL
35	1		*REAR FENDER LH	Dented	1,280.70 FL	*1,280.70 FL
36	1		*REAR FENDER INNER TRIM RH	Cut	693.20 FL	*693.20 FL
37	1		*REAR FENDER INNER TRIM LH	Cut	693.20 FL	*693.20 FL
38	1		*REAR FENDER INNER SHIELD RH	Serviceable	110.00 FL	*- FL
39	1		*REAR FENDER INNER SHIELD LH	Serviceable	110.00 FL	*- FL
40	1		*REAR FENDER GLASS MOULDING RH	Not Necessary	285.00 FL	*- FL
41	1		*REAR FENDER GLASS MOULDING LH	Not Necessary	285.00 FL	*- FL
42	1		*REAR FLOOR PANEL	Repair	985.00 FL	*- FL
43	1		*REAR FLOOR PANEL MAT	Not Necessary	970.00 FL	*- FL
44	1		*REAR FLOOR PANEL TOP BOARD	Bent	1,165.00 FL	*1,165.00 FL
45	1		*REAR EXHAUST PIPE	Serviceable	1,640.20 FL	*- FL
46	1		*REAR EXHAUST PIPE HEAT SHIELD	Serviceable	178.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR EXHAUST PIPE GASKET	Serviceable	90.00 FL	*- FL
48	4		*REAR EXHAUST MOUNTING	Serviceable	180.00 FL	*- FL
49	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
50	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
51	1		*SET REAR TAILLAMP CLIPS	Necessary	50.00 FS	*30.00 FS
52	1		*SET REAR TAILGATE CENTRE REFLECTOR CLIPS	Necessary	20.00 FS	*20.00 FS
53	1		*SET REAR TAILGATE REFLECTOR LAMP CLIPS	Necessary	60.00 FS	*30.00 FS
54	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
55	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
56	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
57	1		*SET REAR TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
58	1		*SET REAR TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
59	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	150.00 FS	*60.00 FS
60	2		*REAR FENDER GLASS SEALANT	Not Necessary	240.00 FS	*- FS
61	1		*REAR TAILGATE SEALANT	Necessary	150.00 FS	*60.00 FS
62	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
63	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
64	1		*REAR FENDER SEALANT	Not Necessary	300.00 FS	*- FS
65	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	600.00 FS	*- FS
66	1		*SET REAR BUMPER REVERSE SENSOR	Cut	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,171.11	12,659.16
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,870.28	3,002.29
Total Parts (\$\$)	17,300.83	9,656.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	2,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,800.00	800.00
3	WIRING & BULK CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR FENDER GLASS	New	120.00	0.00
5	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	50.00
7	TO REMOVE & REFIX REAR REVERSE CAMERA	New	150.00	30.00
8	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	30.00
9	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
10	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	30.00
11	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	50.00
12	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
13	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT ,PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			5,770.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >