



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 81J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N)	SCRATCHED / DEFORMED	985.00	985.00
10	REAR BUMPER CLIP @\$4.50 (N)	NECESSARY	45.00	45.00
1	REAR BUMPER LOWER (N)	CUT	664.30	500.00
1	REAR BUMPER SPONGE (N)	NOT NECESSARY	135.00	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	685.00	-
2	REAR BUMPER REINFORCEMENT BRACKET @\$85.00 (N)	NOT NECESSARY	170.00	-
	LESS 10% DISCOUNT		-	-153.00
			2,684.30	1,377.00
<u>SPECIAL NETT ITEMS</u>				
2	REAR BUMPER PARKING SENSOR @\$490.80 (SN)	FAULTY	981.60	300.00
			981.60	300.00
<u>LABOUR</u>				
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		500.00	250.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		500.00	250.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	30.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	30.00
			1,160.00	560.00
GRAND TOTAL			4,825.90	2,237.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CS/AGI22005468/Sny3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.