# **ESTIMATED ACCIDENT REPAIR COST**



ACCIDENT TIME REPORTED	08:58HRS	
ACCIDENT DATE	26-May-22	
BUS CAPTAIN NAME	LIN YOUQING	
THIRD PARTY CLAIM AGAINST	SMRT BUS - MSFCL	

BUS REGISTRATION NUMBER	SMB8031T	
BUS TYPE (SD/DD)	SD	
BUS ROUTE NUMBER		
BUS ADVERTS (Y/N)	N	

### SECTION 1: MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Т	otal Cost
1	OS FRONT MIRROR ASSY	1	\$	836.00
2	REFLECTIVE STICKER	2	\$	32.00
		7% GST	\$	60.76
		PARTS TOTAL COST	\$	928.76

### SECTION 2: LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TAL COST
TO DISMANTLE & REPLACE :-  OS FRONT MIRROR ASSY REFLECTIVE STICKER		\$	1,300.00
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :-  • OS FRONT CORNER BUMPER  • OS FRONT CORNER EXTERIOR FRP		\$	2,600.00
SPRAY PAINTING :-  OS FRONT CORNER BUMPER OS FRONT CORNER EXTERIOR FRP		\$	1,280.00
	GST	\$	362.60
LABOUR CHARGES \$650 PER DAY	OTAL COST	\$	5,542.60

PAGE 1

# **ESTIMATED ACCIDENT REPAIR COST**



**SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)** 

TOTAL TOWING COST	-
-------------------	---

#### SECTION 4: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN		
		DATE & TIME SURVEY		
			DATE OUT	
BUS TYPE (SD / DD)	SD		TOTAL NUMBER OF DAYS	
LOSS OF USE COST		\$	1,500.00	

SUMMARY			
SECTION NO.	COST		
1	\$	928.76	
2	\$	5,542.60	
3	_		
4	\$	1,500.00	
TOTAL	\$	7,971.36	

PAGE 2