

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC22005473/Rvy3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date:	14/06/2022	
			Code	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XB 8413U	Veh. Inspected	SMM 4558J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	21/22/22/VC00/025905	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	08/06/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS 1.6 ELE	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MR053REH604598029	Colour	WHITE	
	Odometer	256131 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/45Z R17	ECO819	6 mm	
	L/H Front Tyre	215/45Z R17	ECO819	6 mm	
	R/H Rear Tyre	215/45Z R17	ECO819	6 mm	
	L/H Rear Tyre	215/45Z R17	ECO819	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	5. General Information				
	Accident Date	07/06/2022	Inspect Date / Time	09/06/2022 ( 10:41 AM )	
	Survey held at A T PERFORMANCE  160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22005473/Rvy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser