

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22005475/UCY3M4**Date:** 07/07/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SKZ8444H **Insured Vehicle No :** SMH4577E

Date of Loss: 06/06/2022 Nature of Claim: TP Claim No: DMCF2200087H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ8444H**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRY224464

Reg. Date: 04/02/2016 (Man. Year: 2015) Chassis No: MR053REH104541281

Colour: Silver Odometer: 87170 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 12,510.60         | 3,887.17          | 8,623.43          | 68.93         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,700.00          | 1,520.00          | 2,180.00          | 58.92         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>16,210.60</b>  | <b>5,407.17</b>   | <b>10,803.43</b>  | <b>66.64</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,300.00</b>   |                   |               |
| <b>(S\$)</b>                             | 16,210.60         | 4,300.00          | 11,910.60         | 73.47         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,134.74          | 301.00            | 833.74            | 73.47         |
| <b>Nett Amount (S\$)</b>                 | <b>17,345.34</b>  | <b>4,601.00</b>   | <b>12,744.34</b>  | <b>73.47</b>  |

INSPECTION

Date of Assignment: 08/06/2022

Date Inspected: 14/06/2022 Inspected At: Abwin Service Pte Ltd -( 17 Kaki Bukit Road 4 ) (HQ)  
No.17 Kaki Bukit Road 4, #01-60 Bartley Biz Centre  
Singapore 417809

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 07 Jul 2022)                  |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKZ8444H)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's | Amount       |
|-----|-----|----------|------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *BONNET                            | Dented / Bent | 1,322.40 F | *1,322.40 FL |
| 2   | 1   |          | *BONNET HINGE RH                   | Not Necessary | 62.40 F    | *- FL        |
| 3   | 1   |          | *HEADLAMP RH                       | Broken        | 781.20 F   | *781.20 FL   |
| 4   | 1   |          | *HEADLAMP TOP CHROME RH            | Cracked       | 153.20 F   | *153.20 FL   |
| 5   | 1   |          | *FRONT BUMPER                      | Distorted     | 563.00 F   | *541.10 FL   |
| 6   | 1   |          | *FRONT BUMPER SIDE RETAINER RH     | Bent          | 90.40 F    | *90.40 FL    |
| 7   | 1   |          | *FRONT BUMPER REINFORCEMENT        | Repair        | 423.90 F   | *- FL        |
| 8   | 1   |          | *FRONT BUMPER FOG LAMP RH          | Not Necessary | 209.00 F   | *- FL        |
| 9   | 1   |          | *FRONT BUMPER FOG LAMP GARNISH RH  | Grazed        | 119.80 F   | *119.80 FL   |
| 10  | 1   |          | *FRONT FENDER RH                   | Dented        | 965.30 F   | *910.20 FL   |
| 11  | 1   |          | *FRONT FENDER INNERSHIELD RH       | Torn          | 222.00 F   | *222.00 FL   |
| 12  | 1   |          | *FRONT RH LOWER ARM                | Not Necessary | 776.40 F   | *- FL        |
| 13  | 1   |          | *FRONT RH DRIVE SHAFT              | Not Necessary | 1,467.70 F | *- FL        |
| 14  | 1   |          | *FRONT RH KNUCKLE ARM              | Not Necessary | 666.10 F   | *- FL        |
| 15  | 1   |          | *FRONT RH SHOCK ABSORBER           | Not Necessary | 500.40 F   | *- FL        |
| 16  | 1   |          | *STEERING RACK                     | Not Necessary | 2,074.90 F | *- FL        |
| 17  | 1   |          | *FRONT RH KNUCKLE BREARING         | Not Necessary | 177.10 F   | *- FL        |
| 18  | 1   |          | *FRONT RH STABILIZER LINKS         | Not Necessary | 251.10 F   | *- FL        |
| 19  | 1   |          | *FRONT RH STABILIZER BUSHING       | Not Necessary | 41.70 F    | *- FL        |
| 20  | 1   |          | *FRONT GRILLE                      | Cracked       | 680.10 F   | *680.10 FL   |
| 21  | 10  |          | *BONNET CLIPS                      | Necessary     | 50.00 FS   | *50.00 FS    |
| 22  | 10  |          | *HEADLAMP CLIPS                    | Not Necessary | 50.00 FS   | *- FS        |
| 23  | 10  |          | *FRONT BUMPER CLIPS                | Necessary     | 50.00 FS   | *50.00 FS    |
| 24  | 10  |          | *FRONT FENDER INNERSHIELD CLIPS RH | Necessary     | 50.00 FS   | *50.00 FS    |
| 25  | 1   |          | *FRONT RH RIM                      | Repair        | 600.00 FS  | *- FS        |
| 26  | 1   |          | *WASHER TANK                       | Deformed      | 162.50 F   | *162.50 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>12,510.60</b> | <b>5,132.90</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b> | 0.00             | 1,245.73        |
| <b>Total Parts (\$\$)</b>                                 | <b>12,510.60</b> | <b>3,887.17</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                |          |                 |                 |
| 1                               | TO SPRAY PAINT ON AFFECTED AREAS                               | New      | 1,600.00        | 800.00          |
| 2                               | TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS | New      | 1,600.00        | 580.00          |
| 3                               | TO APPLY UNDERCOATING FOR RUST PROOFING                        | New      | 180.00          | 60.00           |
| 4                               | TO CHECK WIRING                                                | New      | 120.00          | 20.00           |
| 5                               | TO CONDUCT WHEEL ALIGNMENT                                     | New      | 200.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                |          | <b>3,700.00</b> | <b>1,520.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >