

Your Ref: -

Date: 06th July 2022

Our Ref: CS1/SCD22005482/Tqy3e2

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMA 539D**INSURED VEHICLE: QX 2076R****ACCIDENT DATE: 03/05/2022**

We thank you for your instruction on 07/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMA 539D from M/s C L Appraiser Pte Ltd.
- b) Final Repair Bill of SMA 539D from M/s Hock Motors Workshop.
- c) Singapore Accident Statement of Vehicles SMA 539D.
- d) Colour damaged vehicle photographs of SMA 539D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMA 539D
Make & Model	: Toyota C-HR Hybrid 1.8S CVT
Chassis Number	: ZYX102118327
Year of Registration	: 2018
Engine Capacity	: 1797 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 539D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR END PANEL	TO REPAIR SEE LABOUR	988.60	-
1	REAR END PANEL INNER GARNISH	DAMAGED	266.60	189.20
1	REAR KEYLESS SENSOR	DAMAGED	400.70	106.90
1	REAR BUMPER	DAMAGED	683.30	545.10
2	REAR BUMPER BRACKETS	DAMAGED	81.40	81.40
1	REAR BUMPER CENTRE GRILLE COVER	DAMAGED	288.30	171.50
1	REAR BUMPER LOWER GARNISH	DAMAGED	557.70	465.10
2	REAR BUMPER REFLECTOR GARNISHES	DAMAGED	175.20	175.20
1	REAR BUMPER REINFORCEMENT	DAMAGED	385.20	382.00
2	REAR BUMPER SIDE RETAINERS	NECESSARY	175.40	175.40
1	REAR BUMPER TOW HOOK COVER	DAMAGED	48.50	27.70
	LESS 25% DISCOUNT		-1,012.73	-579.88
			3,038.17	1,739.62
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			400.00	230.00
<u>LABOUR</u>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	30.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		80.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		750.00	400.00
			1,280.00	950.00
GRAND TOTAL			4,718.17	2,919.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS1/SCD22005482/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.