

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005493/UPA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800143679
Claimant Vehicle No :	SMP8125H	Insured Vehicle No :	SKA2899A
Date of Loss:	08/06/2022	Nature of Claim:	TP
		Claim No:	0862162780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8125H		
Make & Model:	MAZDA 3, 1.5 5DR M-HYBRID ASTINA (A)	Engine No:	P520640778
Reg. Date:	17/10/2019 (Man. Year: 2019)	Chassis No:	JM6BP2SAAK1103130
Colour:	Blue	Odometer:	52664 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R18	Rear Tyre Size:	215/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,414.00	16,216.08	19,197.92	54.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,010.00	3,920.00	2,090.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,424.00	20,136.08	21,287.92	51.39
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	41,424.00	16,000.00	25,424.00	61.38
+ GST 7.00/7.00% (S\$)	2,899.68	1,120.00	1,779.68	61.38
Nett Amount (S\$)	44,323.68	17,120.00	27,203.68	61.38
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		18,222.00		
Global Sum Settlement (S\$)		18,200.00		

INSPECTION

Date of Assignment:	09/06/2022	
Date Inspected:	09/06/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,125.00 F	*- FL
2	1		*FRONT BUMPER	Distorted	1,021.00 F	*1,021.00 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	65.00 F	*65.00 FL
4	1		*FRONT BUMPER BEAM	Not Necessary	542.00 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*FRONT BUMPER TOP GARNISH	Torn	485.00 F	*320.00 FL
7	1		*FRONT BUMPER TOP CHROME MOULDING	Cracked	1,011.00 F	*655.30 FL
8	1		*FRONT BUMPER PDC SENSOR O/S	Not Necessary	185.00 F	*- FL
9	1		*FRONT BUMPER RADAR SENSOR O/S	Serviceable	850.00 F	*- FL
10	1		*HEADLAMP O/S	Cracked	3,300.00 F	*3,200.00 FL
11	1		*WIPER WASHER TANK	Deformed	244.00 F	*168.50 FL
12	1		*FRONT FENDER O/S	Distorted	580.00 F	*416.00 FL
13	1		*FRONT FENDER INNER SHIELD O/S	Torn	248.00 F	*166.50 FL
14	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
15	1		*FRONT FENDER INNER SPONGE O/S	Torn	221.00 F	*102.00 FL
16	1		*FRONT FENDER INNER PANEL O/S	Repair	455.00 F	*- FL
17	1		*FRONT SHOCK ABSORBER O/S	Bent	580.00 F	*392.50 FL
18	1		*FRONT SHOCK ABSORBER TOP MOUNTING O/S	Twisted	190.00 F	*180.40 FL
19	1		*FRONT LOWER ARM O/S	Buckled	788.00 F	*455.30 FL
20	1		*FRONT KNUCKLE ARM O/S	Bent	745.00 F	*376.00 FL
21	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	280.00 F	*280.00 FL
22	1		*FRONT STEERING RACK ASSY	Bent / Jammed	3,250.00 F	*2,255.30 FL
23	1		*FRONT STEERING CROSS MEMBER	Bent / Twisted	2,250.00 F	*2,080.20 FL
24	1		*FRONT DRIVE SHAFT O/S	Serviceable	1,650.00 F	*- FL
25	1		*FRONT DOOR O/S	Badly Dented	1,215.00 F	*1,127.50 FL
26	2		*FRONT DOOR HINGE O/S	Bent	210.00 F	*210.00 FL
27	1		*FRONT DOOR CHECKER O/S	Twisted	148.00 F	*148.00 FL
28	1		*FRONT DOOR INNER RUBBER O/S	Necessary	199.00 F	*168.50 FL
29	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Torn	988.00 F	*611.20 FL
30	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
31	1		*FRONT DOOR GLASS REGULATOR O/S	Bent	399.00 F	*380.00 FL
32	1		*FRONT DOOR OUTER PILLAR O/S	Repair	845.00 F	*- FL
33	1		*FRONT DOOR INNER LOCK O/S	Shorted	488.00 F	*262.30 FL
34	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	85.00 F	*85.00 FL
35	1		*REAR DOOR O/S	Dented / Bent	1,105.00 F	*954.10 FL
36	1		*REAR DOOR INNER RUBBER O/S	Necessary	195.00 F	*168.50 FL
37	1		*REAR DOOR INNER LOCK O/S	Serviceable	488.00 F	*- FL
38	1		*REAR DOOR INNER TRIM BOARD O/S	Torn	950.00 F	*605.30 FL
39	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
40	1		*REAR FENDER O/S	Repair	1,105.00 F	*- FL
41	1		*REAR FENDER UNER SHIELD O/S	Not Necessary	182.00 F	*- FL
42	1		*REAR WHEEL HUB BEARING O/S	Damaged	620.00 F	*520.00 FL
43	1		*REAR TRAILING ARM O/S	Serviceable	845.00 F	*- FL
44	1		*REAR SHOCK ABSORBER O/S	Twisted	305.00 F	*292.40 FL
45	1		*REAR BUMPER	Repair	1,021.00 F	*- FL
46	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	66.00 F	*- FL
47	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 F	*- FL
48	1		*TAILLAMP O/S	Not Necessary	985.00 F	*- FL
49	1		*ROCKER PANEL O/S	Dented / Bent	850.00 F	*608.30 FL
50	1		*ROCKER PANEL GARNISH O/S	Torn	855.00 F	*620.00 FL
51	1		*SET ROCKER PANEL GARNISH CLIPS O/S	Necessary	50.00 F	*50.00 FL
52	1		*FRONT SPORT RIM O/S	Warped	450.00 FS	*450.00 FS
53	1		*REAR SPORT RIM O/S	Warped	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,414.00 20,045.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	3,829.02
Total Parts (S\$)					35,414.00	16,216.08
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRONT PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
5	TO DISMANTLE & REFIX O/S DOOR MECHANISM	New	120.00	120.00
6	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	200.00	120.00
7	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	500.00	350.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
9	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	500.00	300.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,200.00	1,200.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,600.00
Gross Labour Cost (\$\$)			6,010.00	3,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >