

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC22005495/Rqy3e2
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	16/06/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBE 9086T	Veh. Inspected		WC 2187T
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/22/VC05/025891	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		09/06/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CGB45CLSMNB	c.c		13074
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	CGB4CLS00138	Colour		GREEN
	Odometer	360839 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	295/80 R22.5	PROLOAD		8 mm
	L/H Front Tyre	295/80 R22.5	PROLOAD		8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	PROLOAD		8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	PROLOAD		8/8 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.			
5.	General Information				
	Accident Date	04/06/2022	Inspect Date /	Time	13/06/2022 (12:06 PM)
	Survey held at	RS AUTO SERVICES			
		160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22005495/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser