

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22005499/UGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002769  
**Claimant Vehicle No :** SLM4644E **Insured Vehicle No :** SLS2960Z  
 Date of Loss: 05/06/2022 Nature of Claim: TP Claim No: MPC2022D0002959

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4644E**  
 Make & Model: LEXUS ES300H, 2.5 Executive (A) Engine No: 2AR1647292  
 Reg. Date: 31/03/2017 (Man. Year: 2017) Chassis No: JTHBW1GG802147248  
 Colour: Black Odometer: 127227 km  
 Engine Capacity: 2494 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,613.14	2,133.99	1,479.15	40.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,500.00	1,890.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>7,003.14</b>	<b>3,633.99</b>	<b>3,369.15</b>	<b>48.11</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>Nett Liability (S\$)</b>		<b>4,033.99</b>		

INSPECTION

Date of Assignment: 07/06/2022  
 Date Inspected: 09/06/2022 Inspected At: Hup Motor Trading & Service (HQ)  
 Estimated Period of Repair: 4.0 days Blk 9004 Tampines Street 93, #01-120  
 Singapore 528838

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
<b>Parts:</b>	143	LEXUS ES300H 2.5 Executive (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM4644E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*O/S TAIL LAMP ASSY	Cracked	926.60 FN	*926.60 FN
2	2	*O/S TAIL LAMP CLIPS STOPPER	Not Necessary	13.60 FN	*- FN
3	1	*REAR BUMPER	Torn	986.90 FN	*986.90 FN
4	10	*REAR BUMPER CLIPS	Necessary	52.00 FN	*52.00 FN
5	1	*REAR BUMPER O/S SIDE RETAINER	Cracked	122.20 FN	*122.20 FN
6	1	*REAR BUMPER O/S SIDE BRACKET CLIPS	Necessary	6.30 FN	*6.30 FN
7	1	*REAR BUMPER O/S TOP RETAINER	Bent	118.60 FN	*118.60 FN
8	1	*REAR BUMPER SPONGE DAMPER	Not Necessary	137.80 FN	*- FN
9	1	*REAR BUMPER O/S REFLECTOR	Serviceable	60.40 FN	*- FN
10	1	*REAR O/S FENDER	Repair	1,197.10 FN	*- FN
11	8	*REAR O/S FENDER INNER SHIELD CLIPS	Not Necessary	47.20 FN	*- FN
12	1	*REAR WINDSCREEN GLASS OUTER MOULDING	Not Necessary	78.60 FN	*- FN
13	1	*REAR WINDSCREEN GLASS INNER DAM RUBBER DAM RUBBER	Not Necessary	48.80 FN	*- FN
14	1	*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FN	*- FN
15	1	*REAR BUMPER O/S STAY BRACKET	Cracked	158.50 FN	*158.50 FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,014.60</b>	<b>2,371.10</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	401.46	237.11
<b>Total Parts (\$\$)</b>	<b>3,613.14</b>	<b>2,133.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	0.00
3	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER ,FENDER INNER SHIELD ,CUSHION SEAT & NECESSARY PARTS	New	150.00	80.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
5	TO DIAGNOSE & RE-SET TAIL LIGHT & REVERSE SENSOR FAULT CODE	New	150.00	60.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	0.00
7	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,300.00	600.00
8	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,350.00	680.00
<b>Gross Labour Cost (\$)</b>			<b>3,390.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >