

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS22005501/GQY3M4**Date:** 29/07/2022**REFERENCE**

Insured/Claimant:	LIM CHEE TECK	Policy No:	SP2000435666	
Date of Loss:	31/05/2022	Nature of Claim:	OD	Claim No: 202222005088KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2277Z		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 SB URBAN (R18 LED) (A)	Engine No:	27091031251980
Reg. Date:	31/07/2017 (Man. Year: 2017)	Chassis No:	WDD1179422N496420
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$101,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,724.20	715.32	8,008.88	91.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,140.00	760.00	26.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,624.20	2,855.32	8,768.88	75.44
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	10,624.20	1,855.32	8,768.88	82.54
+ GST 7.00/7.00% (\$\$)	743.69	129.87	613.82	82.54
Nett Amount (\$\$)	11,367.89	1,985.19	9,382.70	82.54

INSPECTION

Date of Assignment:	09/06/2022	
Date Inspected:	10/06/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2022)

Parts: 143 MERCEDES-BENZ CLA180 1.6 SB URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ2277Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,433.30 FS	*- FS
2	1		*COMPANY SIGN	Not Necessary	65.25 FS	*- FS
3	1		*RADAR SENSOR	Not Necessary	1,233.72 FS	*- FS
4	1		*IMPACT ABSORBER	Not Necessary	184.71 FS	*- FS
5	1		*TOP BASIC MOUNTING FOR BUMPER	Not Necessary	183.05 FS	*- FS
6	1		*RH TOP BASIC MOUNTING FOR BUMPER	Not Necessary	33.83 FS	*- FS
7	1		*RHF SIDE STABILITY	Not Necessary	66.57 FS	*- FS
8	1		*RHF MOUNTING RAIL	Not Necessary	15.36 FS	*- FS
9	1		*RIGHT AIR FLOW SERRATION	Not Necessary	80.80 FS	*- FS
10	1		*LEFT AIR FLOW SERRATION	Not Necessary	70.96 FS	*- FS
11	1		*FRAME SEGMENT-RADIATOR GRILLE	Cracked	295.45 FS	*295.45 FS
12	1		*STAR CARRIER HOUSING-SILVER	Cracked	180.79 FS	*180.79 FS
13	1		*MERCEDES STAR CARRIER	Cracked	81.30 FS	*81.30 FS
14	1		*MERCEDES STAR	Missing	142.78 FS	*142.78 FS
15	1		*CENTRAL RIGHT TRIM SRIP	Not Necessary	81.96 FS	*- FS
16	1		*CENTRAL LEFT TRIM SRIP	Not Necessary	81.96 FS	*- FS
17	1		*RIGHT HEADLAMP UNIT	Not Necessary	3,099.15 FS	*- FS
18	1		*FRONT SUPPORT PANEL	Not Necessary	1,027.99 FS	*- FS
19	1		*CROSS MEMBER	Not Necessary	350.27 FS	*- FS
20	1		*SUNDRIES	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,724.20** **715.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT	New	380.00	380.00
2	TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT	New	120.00	0.00
3	PANEL BEAT TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
4	RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,900.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >