

## **ESTIMATE FOR SLQ2277Z**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Lim

36 Countryside Road Singapore 789802

Mobile: +6596363306

Vehicle & Document Information

WIP No 57440

Reg No/Reg Date SLQ2277Z / 31/07/2017

Date In/Mileage

9-4-5 Chassis No WDD1179422N496420

Engine No

27091031251980

Make/Model

MB/MB CLA 180 S/B (X117) "FACELIFT"

Colour/Trim

027 787 Mountain Gr/ 041 151 Lther ARTIC

| Account No Terms Date/Time Printed CSE Operator                    |  |
|--|--|
| CSM00128 Cash 09/06/2022/11:53 VS 356 / Vinc                       | ent Seah   |
| Description of Goods / Services                                    | Qty Unit Price Disc% Amount  |
| Z REQUEST  |  |
| Customer Request   | IAL TAX INVOICE  |
|  |  |
| POLICY NO/ACC DATE :SP2000435666-01 //                             | ·  |
| DRIVE IN/EXCESS : 09.06.2022 //                                    | and the second s |
| DATE IN/DATE SURVEY:   | The second second  |
| BY/AUTHRIZED ON :  | 15.00  |
| M BPNSUN<br>SUNDRIES   | 15.00  |
| A BPILAB   | 0.10 / 380.00  |
| USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY T    | 0.10   |
| IDENTIFICATION STANDARD. NETT                                      |  |
| A BPILAB   | X NN 120.00  |
| TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NEXT                      | 120.00   |
| A BPILAB   | 960 1200.00  |
| PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH N    |  |
| BODY PANELS WITH REFINISH  |  |
| A BPIRES   | 800 1200.00  |
| RESPRAY ON FRONT BUMPER AND ACCIDENT AFFECTED AREA                 |  |
| M FRONT BUMPER NN  | 1.00 1433.30 00.00 1433.30   |
| M COMPANY SIGN X NN  | 1.00 65.25 00.00 65.25   |
| M RADAR SENSOR 🛪 🕦   | 1.00 1233.72 00.00 1233.72   |
| M IMPACT ABSORBER X NN   | 1.00 184.71 00.00 184.71   |
| M TOP BASIC MOUNTING FOR BUMPER X NN                               | 1.00 183.05 00.00 183.05   |
| M RH TOP BASIC MOUNTING FOR BUMPER X NN                            | 1.00 33.83 00.00 33.83   |
| M RHF SIDE STABILITY X NN  | 1.00 66.57 00.00 66.57   |
| M RHF MOUNTING RAIL X NN   | 1.00 15.36 00.00 15.36   |
| M RIGHT AIR FLOW SERRATION X NN                                    | 1.00 80.80 00.00 80.80   |
| M LEFT AIR FLOW SERRATION X NN                                     | 1.00 70.96 00.00 70.96   |
| M FRAME SEGMENT-RADIATOR GRILLE V CRA                              | 1.00 295.45 00.00 295.45<br>1.00 180.79 00.00 180.79   |
| M STAR CARRIER HOUSING-SILVER   CRA  M MERCEDES STAR CARRIER   CRA | 1.00 81.30 00.00 81.30   |
| M MERCEDES STAR CARRIER V CRA                                      | 1.00 142.78 00.00 142.78   |
| II HERGEDES STAN A MIS   | 1.00 142.70 00.00  |
| Confirmed & accepted by  | 2055 20  |

2855.32

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





## **ESTIMATE FOR SLQ2277Z**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Lim

36 Countryside Road Singapore 789802

Mobile: +6596363306

Vehicle & Document Information

WIP No 57440

Reg No/Reg Date / 31/07/2017 **SLQ2277Z** 

Date In/Mileage

Chassis No WDD1179422N496420

27091031251980 Engine No

Make/Model MB/MB CLA 180 S/B (X117) "FACELIFT"

Colour/Trim 027 787 Mountain Gr/ 041 151 Lther ARTIC

| Account No                           | Terms                              | Date/Time Printed                  | CSE                 | Operator           |                      |   |                           |
|--------------------------------------|------------------------------------|------------------------------------|---------------------|--------------------|----------------------|---|---------------------------|
| CSM00128                             | Cash                               | 09/06/2022/ 13                     | .:53 VS             | 356 / Vincent Seah |                      |   |                           |
| 3 14162 21                           |                                    | Description of                     | of Goods / Services |                    | Qty                  | Unit Price Disc%                            | Amount                    |
| M CENTRAL<br>M CENTRAL<br>M RIGHT HE | RIGHT IR<br>LEFT TRIM<br>ADLAMP UN | IM SRIPX NN<br>SRIPX NN<br>IT X NN | AN (                | FFICIAL            | 1.00<br>1.00<br>1.00 | 81.96 00.00<br>81.96 00.00<br>3099.15 00.00 | 81.96<br>81.96<br>3099.15 |
|                                      | PPORT PANI<br>MBER X NN            |                                    |                     |                    | 1.00                 | 1027.99 00.00<br>350.27 00.00               |                           |

Not Authorised

Excess: TBA

3 Days

Guo Qiang - LKK

Before paint photos After repair photos

HP: 82880282

GuoQiang@lkkauto.com

10/06/2022

Confirmed & accepted by

Nett

11,624.20

7% GST on 11624.20

813.69

**Total Payable** 

12,437.89

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

