

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005509/AVCE2**Date:** 02/11/2022**REFERENCE**

Insured/Claimant:	ONG CHEAN WEI	Policy No:	1900152610-02	
Date of Loss:	03/06/2022	Nature of Claim:	OD	Claim No: 2700154610SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9288A		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK086850
Reg. Date:	31/08/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF56KA071542
Colour:	Blue	Odometer:	25484 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,657.00	8,128.00	25,529.00	75.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,372.00	2,772.00	3,600.00	56.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	40,029.00	10,900.00	29,129.00	72.77
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	39,229.00	10,100.00	29,129.00	74.25
+ GST 7.00/7.00% (\$\$)	2,746.03	707.00	2,039.03	74.25
Nett Amount (\$\$)	41,975.03	10,807.00	31,168.03	74.25

INSPECTION

Date of Assignment:	09/06/2022	
Date Inspected:	09/06/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,576.00 FS	*2,060.80 FS
8	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	116.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	209.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,058.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
15	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
16	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
17	1		*FRONT BUMPER BRACKET LOCK CARRIER	Cracked	154.00 FS	*122.80 FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*2.88 FS
19	4		*FRONT BUMPER POP RIVET	Not Necessary	4.00 FS	*- FS
20	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	530.00 FS	*- FS
21	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
22	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	598.00 FS	*- FS
23	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
24	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
25	2		*BONNET HINGE - LH / RH	Not Necessary	932.00 FS	*- FS
26	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
27	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
28	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
30	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - OUTER	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
33	2		*HEADLIGHT - LH / RH	Not Necessary	16,832.00 FS	*- FS
34	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
35	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	34.00 FS	*- FS
36	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	100.00 FS	*- FS
37	1		*OUTSIDE TEMPERATURE SENSOR	Not Necessary	21.00 FS	*- FS
38	2		*RADIATOR AIR GUIDE INNER - LH / RH	Not Necessary	72.00 FS	*- FS
39	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Not Necessary	38.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
41	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
42	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
43	1		*SUNDRIES	Necessary	400.00 FS	*16.32 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 33,657.00 8,128.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,372.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >