

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005510/VPA3Q2**Date:** 13/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SJG9140P **Insured Vehicle No :** GBK1412G

Date of Loss: 28/05/2022 Nature of Claim: TP Claim No: MFL2022D0002760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG9140P**

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910105020

Reg. Date: 21/07/2008 (Man. Year: 2008) Chassis No: JMYSRCY2A8U008447

Colour: Blue Odometer: 147884 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,889.11	1,170.20	718.91	38.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,370.00	1,090.00	44.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,349.11	2,540.20	1,808.91	41.59
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	4,349.11	2,000.00	2,349.11	54.01
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 09/06/2022

Date Inspected: 10/06/2022 Inspected At: Sin Hwee Motor Pte Ltd (HQ)
Blk 3023A, Ubi Road 1, #01-59
Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Oct 2022)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJG9140P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Dented	689.11 F	*689.11 FN
2	1		*REAR BUMPER	Repair	650.00 FS	*- FS
3	1		*SPORT RIM	Scratched	550.00 FS	*550.00 FS
					Sub Total (\$\$)	1,889.11
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	1,889.11
						1,170.20

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR FENDER INCLUDING KNOCKING ,HEATING AND CUTTING TO REPLACE AND ALIGN REAR BUMPER	New	1,200.00	600.00
2	REMOVE AND REFIX WINDSCREEN	New	180.00	120.00
3	WINDSCREEN SEALANT	New	100.00	50.00
4	TO SPRAY PAINT REAR FENDER ,REAR DOOR AND REAR BUMPER	New	900.00	600.00
5	COMPUTERIZED ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			2,460.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >