

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2302502

3 ANSON ROAD #16-00 INV Date 20/04/2023

SPRINGLEAF TOWER Reference CC6/CTI22005512/Aya3q2 SINGAPORE 079909

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLH 3005H

Insured Veh. GBF 3347A

Claim No. SNM22D203885/C02

Policy No. DMCVSNW00101222100

Accident Date 30/05/2022

Inspection Date 08/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	SURANCE (S) PTE LTD	Ref:	CC6/CTI22005512/Aya3q2			
	3 ANSON ROAD # SPRINGLEAF TO\	16-00 VERSINGAPORE 079909	Date	: 20/04/2023			
			Code	e: CTI			
1.		Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBF 3347A	Veh. Inspected	SLH 3005H			
	Policy No.	DMCVSNW00101222100	Coverage (\$)	0.00			
	Claim No.	SNM22D203885/C02	Excess (\$)	0.00			
	Assign From		Assign Date	08/06/2022			
2.		Vehicle Parti	culars & Condition				
	Make & Model	B.M.W. X1	c.c	1499			
	Engine No.	HIDDEN	Year of Reg.	2016			
	Chassis No.	WBAHS120605F02420	Colour	GREY			
	Odometer	102834 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Conditi	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	225/50 R18	HANKOOK	6 mm			
	L/H Front Tyre	225/50 R18	HANKOOK	6 mm			
	R/H Rear Tyre	225/50 R18	HANKOOK	6 mm			
	L/H Rear Tyre	225/50 R18	HANKOOK	6 mm			
4.		Description	on of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.						
	DAMAGES SEE DETAILS.						
5.		Genera	I Information				
	Accident Date	30/05/2022	Inspection Date	08/06/2022			
	Survey held at	KANG CAR REPAIRERS PTE L	TD				
		NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883					
5a.		R	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.		Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	•						



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 3005H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	DEFORMED	1,327.45	1,327.45
1	FRT BUMPER SIDE RETAINER LH	NECESSARY	75.10	75.10
1	FRT FENDER PROTECTOR LH	TO REPAIR SEE LABOUR	315.70	-
1	FRT BUMPER PARKING SENSOR LH	DAMAGED	286.80	286.80
1	HEADLAMP LH	CUT	2,728.95	2,728.95
1	FRT FOG LAMP LH	NOT NECESSARY	366.90	-
1	FRT FOG LAMP COVER LH	NOT NECESSARY	102.10	-
	LESS 5% DISCOUNT		-260.15	-
	LESS 10% DISCOUNT		-	-441.83
			4,942.85	3,976.47
	SPECIAL NETT ITEMS			
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRT BUMPER PROTECTOR CLIPS (SN)	NOT NECESSARY	40.00	-
			100.00	30.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	(FRONT) TO SPRAY PAINTING.		450.00	350.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING /WELDING WORKS .INCLUSIVE OF THE REPAIR OF FRT FENDER PROTECTOR LH .		500.00	350.00
	TO PROGRAM.		300.00	120.00
			1,300.00	850.00
	GRAND TOTAL		6,342.85	4,856.47

RECOMMENDED COST OF LUMP SUM REPAIRS		3,850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI22005512/Aya3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 3005H

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315





