

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIS22005515/ENY3E2

**Date:** 29/07/2022

### REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001522235  
**Claimant Vehicle No :** SNC4082E **Insured Vehicle No :** SMJ2303G  
Date of Loss: 08/06/2022 Nature of Claim: TP Claim No: 202222005150FR

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC4082E**  
Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25510741  
Reg. Date: 04/10/2019 (Man. Year: 2019) Chassis No: MRHFC5650KT000676  
Colour: Silver Odometer: 24787 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm  
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,112.00	2,274.00	2,838.00	55.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,860.00	1,000.00	34.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,972.00</b>	<b>4,134.00</b>	<b>3,838.00</b>	<b>48.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>(S\$)</b>	7,972.00	2,400.00	5,572.00	69.89
<b>+ GST 7.00/7.00% (S\$)</b>	558.04	168.00	390.04	69.89
<b>Nett Amount (S\$)</b>	<b>8,530.04</b>	<b>2,568.00</b>	<b>5,962.04</b>	<b>69.89</b>

### INSPECTION

Date of Assignment: 09/06/2022  
Date Inspected: 10/06/2022 Inspected At: Accord Auto Services Pte Ltd (Bukit Merah)  
BLK 1009 BUKIT MERAH LANE 3, #01-80  
Singapore 159723  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2022)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNC4082E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	780.00 FL	*580.00 FL
2	1		*REAR BOOT OUTER	Broken	220.00 FL	*110.00 FL
3	1		*REAR BOOT EMBLEM	Necessary	60.00 FL	*60.00 FL
4	1		*REAR BOOT CIVIC	Necessary	85.00 FL	*65.00 FL
5	1		*REAR BOOT I-VTEC	Necessary	95.00 FL	*65.00 FL
6	1		*REAR BOOT LOCK	Not Necessary	268.00 FL	*- FL
7	2		*REAR BOOT HINGE	Not Necessary	180.00 FL	*- FL
8	2		*REAR BOOT HINGE COVER	Not Necessary	150.00 FL	*- FL
9	2		*REAR BOOT LIGHT	Not Necessary	370.00 FL	*- FL
10	1		*REAR LH LAMP	Broken	320.00 FL	*320.00 FL
11	1		*REAR RH LAMP	Not Necessary	320.00 FL	*- FL
12	2		*REAR LAMP CLIPS	Not Necessary	12.00 FL	*- FL
13	1		*REAR BUMPER	Broken	680.00 FL	*680.00 FL
14	2		*REAR BUMPER LOWER WITH CHROME	Cut	365.00 FL	*365.00 FL
15	1		*REAR BUMPER TOW COVER	Cut	45.00 FL	*45.00 FL
16	1		*REAR BUMPER SIDE RETAINER	N/S Broken	120.00 FL	*60.00 FL
17	1		*REAR LH BUMPER REFLECTOR GARNISH	Not Necessary	145.00 FL	*- FL
18	1		*REAR LH BUMPER REFLECTOR	Not Necessary	110.00 FL	*- FL
19	1		*REAR BUMPER SENSOR (4PCS)	Broken (1pc only)	880.00 FL	*220.00 FL
20	1		*SET REAR BUMPER SENSOR SEAL	Necessary	60.00 FL	*60.00 FL
21	1		*REAR END PANEL	Repair	520.00 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.00 FL	*- FL
23	1		*REAR RUBBER	Crushed	175.00 FL	*175.00 FL
24	1		*SET CAR PLATE NUMBER WITH HOLDER	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
26	2		*SET REAR LH & RH FENDER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*SET REAR INNER TRIM BOARD / COMPARTMENT CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,340.00</b>	<b>2,835.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,228.00	561.00
<b>Total Parts (\$\$)</b>	<b>5,112.00</b>	<b>2,274.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	800.00	800.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	800.00
3	ANTI RUST TREATMENT	New	100.00	30.00
4	TO REMOVE / REFIX / REPLACE REVERSE SENSOR	New	180.00	30.00
5	TO REMOVE / REFIX REAR REVERSE CAMERA	New	150.00	50.00
6	TO REMOVE / REFIX INNER COMPARTMENT & CARPET TO FACILITATE REPAIR	New	280.00	80.00
7	COMPUTER DIAGNOSTIS AFTER REPAIR	New	350.00	70.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,860.00</b>	<b>1,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >