



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: NG STACEY			Ref: CS3/ASM21008928/Rvce2-1 Date: 01/08/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	YP 7530K	Veh. Inspected	YQ 2538S	
Policy No.	VFX/P1847906	Coverage (\$)	0.00	
Claim No.	S1M03FLP	Excess (\$)	0.00	
Assign From	NG STACEY	Assign Date	10/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HINO XZU710R 14FT 8.5T	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JHHUCW2F60K033745	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/75 R17.5	TRIANGLE	7 mm	
L/H Front Tyre	215/75 R17.5	TRIANGLE	7 mm	
R/H Rear Tyre	215/75 R17.5 (D)	TRIANGLE	7/7 mm	
L/H Rear Tyre	215/75 R17.5 (D)	TRIANGLE	7/7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/08/2021	Inspection Date	22/06/2022	
Survey held at	7 Penjuru Close			
Repairer	VFIX AUTO SERVICE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	