



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS3/ASM22003361/Tvy3e2-1 Date: 05/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	YP 5498J	Veh. Inspected	SLG 3259Y
	Policy No.	GA607174	Coverage (\$)	0.00
	Claim No.	S2M03Y7M	Excess (\$)	0.00
	Assign From	KHONG LYNN	Assign Date	10/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HARRIER	c.c	1986
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ZSU600070203	Colour	MAROON
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	06/04/2022	Inspection Date	15/06/2022
	Survey held at	YEOW KOON MOTOR SPRAY PAINTING BLK 9002 TAMPINES STREET 93 #01-34 TAMPINES INDUSTRIAL PARK A . SINGAPORE 528836		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	