



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5744J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT	500.00	500.00
1	FRONT BUMPER RH BRACKET	DISTORTED	110.00	110.00
1	FRONT BUMPER RH SIDE PAD	MISSING	220.00	220.00
1	RH HEADLAMP	CRACKED	290.00	290.00
1	RH SIGNAL LAMP	BROKEN	170.00	170.00
1	RH HEADLAMP SIDE REFLECTOR	MISSING	105.00	105.00
1	FRONT GRILLE	CRACKED	550.00	550.00
1	FRONT PANEL EMBLEM (FUSO)	NECESSARY	70.00	70.00
1	FRONT WIPER GARNISH	CRACKED	180.00	180.00
1	FRONT PANEL (BIG)	BENT	1,200.00	1,200.00
1	FRONT RH CORNAL PANEL	CRACKED	270.00	270.00
1	AIRCON EVAPORATOR	MTG CRACKED	980.00	980.00
1	AIR CON GAS DISCHARGE HOSE	DENTED	155.00	155.00
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	190.00	190.00
1	FRT CABIN RH MOUNTING BRACKET (ADDITIONAL)	CRACKED	480.00	480.00
1	FRT CABIN RH MOUNTING (ADDITIONAL)	CRACKED	150.00	150.00
1	BRAKE PIPE (ADDITIONAL)	DENTED	180.00	180.00
1	FRT RH DOOR INNERLOCK (ADDITIONAL)	DENTED	185.00	185.00
1	CABIN REAR AIR DUCTING (ADDITIONAL)	CRACKED	245.00	245.00
			6,230.00	6,230.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	35.00	20.00
			35.00	20.00
<u>LABOUR</u>				
REMOVE AND REFIX FRONT WINDSCREEN GLASS.			100.00	100.00
REMOVE AND REFIX AIRCON CHECK,VACUUM & REFILL GAS.			100.00	100.00
REMOVE & REFIX DASHBOARD METER ASSY .			280.00	250.00
PANEL BEATING AND STRAIGHTEN FRT RH WINDSCREEN PILLAR.			800.00	700.00

Report Ref No. CS/SMO22005523/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY ON FRT PANEL ,CORNAL PANEL ,FRT GRILLE ,FRT RH WS PILLAR ,FRT RH DOOR ,FRT BUMPER ,CABIN RR PANEL .		800.00	720.00
	TO REMOVE ALUMINIUM CANOPY & ATTACHMENT, SUPPLY 1 SET ASSY FRT WOODEN STRUCTURE ,FRT STRUCTURE BOARD AND INSTALLATION.		1,700.00	1,400.00
	REMOVE ALUMINIUM CANOPY & ATTACHMENT SUPPLY 2 SIDE SLIDING CANVAS ,FRT WINDOW GLASS, 4 PCS PILLAR,1 PC REAR ROLL DOWN CANVAS AND 1 SET ROOF TOP STRUCTURE ASSY .		3,800.00	3,700.00
			7,580.00	6,970.00
GRAND TOTAL			13,845.00	13,220.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,550.00
LESS EXCESS			-750.00
NETT LIABILITY			9,800.00

Report Ref No. CS/SMO22005523/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.