

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005534/EVY3Q2**Date:** 28/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00111332202

Claimant Vehicle No : SLC9420D **Insured Vehicle No :** SLZ5501J

Date of Loss: 23/05/2022 Nature of Claim: TP Claim No: SNM22D203603/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC9420D**

Make & Model: HONDA SHUTTLE, 1.5 G (A) Engine No: L15B3536506

Reg. Date: 30/05/2016 (Man. Year: 2016) Chassis No: GK81005546

Colour: Blue Odometer: 326353 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,732.00	1,777.60	1,954.40	52.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,290.00	90.00	6.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,112.00	3,067.60	2,044.40	39.99
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	5,112.00	2,450.00	2,662.00	52.07
+ GST 8.00/8.00% (\$\$)	408.96	196.00	212.96	52.07
Nett Amount (\$\$)	5,520.96	2,646.00	2,874.96	52.07

INSPECTION

Date of Assignment: 10/06/2022

Date Inspected: 10/06/2022 Inspected At: LION CITY RENTALS (HQ)
NO. 4 JALAN BESUT
Singapore 619557

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Mar 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9420D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/L FENDER	Dented	2,000.00 FL	*1,172.00 FL
2	1		*R/L FENDER INNER LINER	Not Necessary	240.00 FL	*- FL
3	1		*R/L DOOR	Dented	1,575.00 FL	*1,050.00 FL
4	1		*LH SIDE SKIRT	Repair	750.00 FL	*- FL
5	1		*SET REAR LH FENDER INNER LINEAR CLIPS	Not Necessary	80.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					4,645.00	2,222.00
- List Item Discount on L Items 20.00/20.00% (S\$)					913.00	444.40
Total Parts (S\$)					3,732.00	1,777.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE FRONT BUMPER ,F/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	600.00	600.00
2	TO RESPRAY REAR LH FENDER ,REAR DOOR LH AND LH SIDE SKIRT	New	700.00	660.00
3	TO APPLY RUSTPROOFING /TUFFCOATING TREAMENT TO REPLACED PARTS	New	80.00	30.00
Gross Labour Cost (\$\$)			1,380.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >