

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005535/EQY3M4**Date:** 14/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00095922201	
Claimant Vehicle No :	SMH1475K	Insured Vehicle No :	SJT9048E	
Date of Loss:	09/06/2022	Nature of Claim:	TP	Claim No: SNM22D204065/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH1475K		Engine No:	LEB7101942
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)		Chassis No:	GP72001392
Reg. Date:	14/01/2019 (Man. Year: 2018)		Odometer:	117098 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,383.00	958.80	424.20	30.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	730.00	1,050.00	58.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,163.00	1,688.80	1,474.20	46.61
Approved Total (Overridden) (\$\$)		1,350.00		
(\$\$)	3,163.00	1,350.00	1,813.00	57.32
+ GST 7.00/7.00% (\$\$)	221.41	94.50	126.91	57.32
Nett Amount (\$\$)	3,384.41	1,444.50	1,939.91	57.32

INSPECTION

Date of Assignment:	10/06/2022	
Date Inspected:	20/06/2022	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jul 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH1475K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,151.00 FL	*980.00 FL
2	2		*REAR BUMPER SIDE RETAINER LH/RH @2*\$25	Broken	50.00 FL	*50.00 FL
3	1		*BOOT LID EMBLEM HYBRID	Necessary	75.00 FL	*75.00 FL
4	1		*BOOT LID EMBLEM SHUTTLE	Necessary	56.00 FL	*56.00 FL
5	1		*BOOT LID LOGO BADGE	Not Necessary	28.00 FL	*- FL
6	1		*BOOT LID (REPAIR REFER TO LABOR) (NPA)	Repair	0.00 FL	*- FL
7	1		*END PANEL (REPAIR REFER TO LABOR) (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
9	1		*REAR REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
10	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,655.00	1,191.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	272.00	232.20
Total Parts (\$\$)	1,383.00	958.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	800.00	250.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	400.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
5	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	90.00	20.00
Gross Labour Cost (\$)			1,780.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >