

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22005540/KQY3M4**Date:** 29/07/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000709754
Claimant Vehicle No : SKX8215M **Insured Vehicle No :** SKR174G
 Date of Loss: 09/06/2022 Nature of Claim: TP Claim No: 202222005165JK-FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX8215M**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4870140
 Reg. Date: 11/03/2009 (Man. Year: 2009) Chassis No: MR053ZEE106141692
 Colour: Metallic Grey Odometer: 329668 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Habilead 3 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Habilead 3 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,264.65	3,594.82	1,669.83	31.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,640.00	1,220.00	42.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,124.65	5,234.82	2,889.83	35.57
Approved Total (Overridden) (S\$)		4,150.00		
Nett Amount (S\$)	8,124.65	4,150.00	3,974.65	48.92

INSPECTION

Date of Assignment: 10/06/2022
 Date Inspected: 14/06/2022 Inspected At: Massive Trading & Auto
 Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2
 Singapore 569541
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX8215M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER	Bent	497.10 FL	*497.10 FL
2	1		*FRONT O/S FENDER INNERSHIELD	Serviceable	175.20 FL	*- FL
3	1		*FRONT O/S FENDER EMBLEM	Not Necessary	40.10 FL	*- FL
4	1		*FRONT O/S DOOR	Bent	1,075.10 FL	*1,075.10 FL
5	1		*FRONT O/S DOOR PROTECTOR	Bent	187.20 FL	*187.20 FL
6	1		*FRONT O/S DOOR VIEW MIRROR	Mtg Distorted	550.70 FL	*550.70 FL
7	1		*FRONT O/S DOOR VIEW MIRROR LAMP	Cracked	176.20 FL	*176.20 FL
8	1		*FRONT O/S DOOR GLASS OUTER MOULDING	Serviceable	155.30 FL	*- FL
9	1		*FRONT O/S INNER LOCK	Repair	325.10 FL	*- FL
10	1		*FRONT O/S DOOR OUTER HANDLE	Serviceable	165.20 FL	*- FL
11	1		*FRONT O/S DOOR FRAME BLACK STICKER	Necessary	65.70 FL	*65.70 FL
12	1		*FRONT O/S DOOR INNER TRIM BOARD	Mtg Cracked	576.10 FL	*576.10 FL
13	1		*FRONT O/S DOOR GLASS REGULATOR	Distorted	195.20 FL	*195.20 FL
14	1		*FRONT O/S DOOR GLASS REGULATOR MOTOR	Jammed	355.70 FL	*355.70 FL
15	1		*FRONT O/S DOOR RUBBER	Serviceable	175.30 FL	*- FL
16	1		*FRONT O/S WINDSCREEN PILLAR	Repair	675.80 FL	*- FL
17	1		*FRONT O/S WINDSCREEN PILLAR WEATHERSTRIP	Serviceable	205.30 FL	*- FL
18	1		*FRONT O/S DOOR HINGE (2PCS)	Lower Bent	291.40 FL	*145.70 FL
19	1		*FRONT O/S DOOR CHECKER	Distorted	105.10 FL	*105.10 FL
20	1		*O/S ROCKER PANEL GARNISH	Distorted	687.10 FL	*687.10 FL
21	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	110.10 FL	*- FL
22	1		*REAR O/S DOOR PROTECTOR	Necessary	176.20 FL	*176.20 FL
23	1		*FRONT WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,006.20	4,793.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,741.55	1,198.28
Total Parts (\$\$)	5,264.65	3,594.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING AND CUTTING ETC	New	1,000.00	700.00
2	TO PUTTY & SPRAY PAINT FRONT & REAR ACCIDENT AFFECTED PORTION	New	1,000.00	800.00
3	CHECK/RECONNECT WIRING	New	40.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	150.00	60.00
5	REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIR	New	120.00	0.00
6	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR ON REAR FENDER	New	200.00	60.00
7	REMOVE/REFIT FRONT DASHBOARD TO FACILITATE REPAIR	New	350.00	0.00
Gross Labour Cost (\$\$)			2,860.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >