

TPMS LG.

SMD 120L.

Veron.

Harold Freed.

GB71062894.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

841.10. ✓

Rear Bumper

Deformed

30(SN). ✓

Rear Bumper Clips. Nec

Not
rec

45.5 x 2 = 91 x

Rear Bumper Side Holder x 02

Rear Bumper Reflector RH. Cribd
rec

75-80. ✓

Rear Bumper Lower Protector (1 Set). ~~100(SN)~~. 50(SN)

Reverse Sensor. Xte rec 280(SN). x.

916.90.

S.N: 80.

733.52

Panel Beating

~~300~~ 200

Spray Painting.

~~300~~ 200.

Wiring.

~~50~~ 30 480.

To remove reverse sensor.

~~100~~ 50

total: 1293.52

c/s: 1k.

02 hrs.