

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22005542/AVCE2**Date:** 09/12/2022**REFERENCE****Insured/Claimant:** TAN SIEW FOONG (CHEN XIUFENG)**Policy No:** 7220007934**Date of Loss:** 03/06/2022**Nature of Claim:** OD **Claim No:** 8070314433SG**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SGQ1219H**Make & Model:** AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)**Engine No:** DFY293516**Reg. Date:** 24/01/2022 (Man. Year: 2021)**Chassis No:** WAUZZZGY2NA005888**Colour:** Blue**Odometer:** 10458 km**Engine Capacity:** 1498 cc**Market Value/New Car Price:** S\$163,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 225/45R17**Rear Tyre Size:** 225/45R17**Front Left Side:** Bridgestone 6 mm**Rear Left Side:** Bridgestone 6 mm**Front Right Side:** Bridgestone 6 mm**Rear Right Side:** Bridgestone 6 mm*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 11,437.00         | 1,580.00          | 9,857.00          | 86.19         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 3,572.00          | 2,022.00          | 1,550.00          | 43.39         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>15,009.00</b>  | <b>3,602.00</b>   | <b>11,407.00</b>  | <b>76.00</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | 1,050.63          | 252.14            | 798.49            | 76.00         |
| <b>Nett Amount (S\$)</b>      | <b>16,059.63</b>  | <b>3,854.14</b>   | <b>12,205.49</b>  | <b>76.00</b>  |

**INSPECTION****Date of Assignment:** 11/06/2022**Date Inspected:** 10/06/2022 **Inspected At:**

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

**Estimated Period of Repair:** 3.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars  | Condition     | Repairer's                | Amount                    |
|-----|-----|----------|--|---------------|---------------------------|---------------------------|
| 1   | 1   |          | *FRONT BUMPER  | Repair        | 1,677.00 FS               | *- FS                     |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                             | Not Necessary | 290.00 FS                 | *- FS                     |
| 3   | 1   |          | *FRONT BUMPER CLOSING ELEMENT-RH                       | Not Necessary | 130.00 FS                 | *- FS                     |
| 4   | 1   |          | *FRONT BUMPER GRILLE-LOWER CENTER                      | Cracked       | 433.00 FS                 | *346.00 FS                |
| 5   | 1   |          | *FRONT BUMPER CLOSING ELEMENT-LOWER CENTER             | Not Necessary | 265.00 FS                 | *- FS                     |
| 6   | 1   |          | *FRONT BUMPER AIR GUIDE-RH                             | Not Necessary | 67.00 FS                  | *- FS                     |
| 7   | 1   |          | *FRONT BUMPER SPOILER                                  | Deformed      | 326.00 FS                 | *260.40 FS                |
| 8   | 1   |          | *FRONT BUMPER TRIM COVER-RH                            | Repair        | 104.00 FS                 | *- FS                     |
| 9   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE-RH                      | Not Necessary | 171.00 FS                 | *- FS                     |
| 10  | 1   |          | *FRONT PARKING AID SENSOR SUPPORT-RH                   | Not Necessary | 43.00 FS                  | *- FS                     |
| 11  | 1   |          | *RADIATOR GRILLE                                       | Cut           | 932.00 FS                 | *745.60 FS                |
| 12  | 1   |          | *RADIATOR GRILLE CLOSING ELEMENT-CENTER                | Damaged       | 210.00 FS                 | *168.00 FS                |
| 13  | 1   |          | *FRONT BUMPER REINFORCEMENT BEAM                       | Not Necessary | 748.00 FS                 | *- FS                     |
| 14  | 1   |          | *FRONT BUMPER FOAM FILLER PIECE                        | Not Necessary | 120.00 FS                 | *- FS                     |
| 15  | 2   |          | *FRONT BUMPER GUIDE SECTION-LH/RH                      | Not Necessary | 108.00 FS                 | *- FS                     |
| 16  | 1   |          | *FRONT BUMPER TOP COVER                                | Not Necessary | 93.00 FS                  | *- FS                     |
| 17  | 1   |          | *CAUTION STICKER                                       | Not Necessary | 16.00 FS                  | *- FS                     |
| 18  | 1   |          | *AIR COND STICKER                                      | Not Necessary | 9.00 FS                   | *- FS                     |
| 19  | 1   |          | *HORN-RH   | Not Necessary | 161.00 FS                 | *- FS                     |
| 20  | 1   |          | *HORN SUPPORT-RH                                       | Not Necessary | 35.00 FS                  | *- FS                     |
| 21  | 2   |          | *HORN SUPPORT-UPPER                                    | Not Necessary | 54.00 FS                  | *- FS                     |
| 22  | 2   |          | *FRONT PARKING AID SENSOR AIR GUIDE GRILLE-INNER/OUTER | Not Necessary | 558.00 FS                 | *- FS                     |
| 23  | 4   |          | *FRONT PARKING AID SENSOR SEAL RING                    | Not Necessary | 32.00 FS                  | *- FS                     |
| 24  | 1   |          | *HEADLIGHT-RH  | Not Necessary | 4,084.00 FS               | *- FS                     |
| 25  | 1   |          | *LIFT CYLINDER-RH                                      | Not Necessary | 211.00 FS                 | *- FS                     |
| 26  | 1   |          | *LIFT CYLINDER-HOSE                                    | Not Necessary | 108.00 FS                 | *- FS                     |
| 27  | 1   |          | *RADIATOR AIR GUIDE                                    | Not Necessary | 42.00 FS                  | *- FS                     |
| 28  | 1   |          | *FRONT NO PLATE  | Necessary     | 60.00 FS                  | *60.00 FS                 |
| 29  | 1   |          | *SUNDRIES  | Not Necessary | 350.00 FS                 | *- FS                     |
|     |     |          |  |               | <b>Total Parts (\$\$)</b> | <b>11,437.00 1,580.00</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New      | 480.00          | 480.00          |
| 2                              | TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE   | New      | 350.00          | 0.00            |
| 3                              | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED                   | New      | 1,050.00        | 500.00          |
| 4                              | TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER  | New      | 1,500.00        | 850.00          |
| 5                              | TO CARRY OUT DIAGNOSTIC CHECK   | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>3,572.00</b> | <b>2,022.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >