

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005544/UPA3Q2**Date:** 05/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MCV0002611
Claimant Vehicle No : SLP3146S **Insured Vehicle No :** GBH9672K
 Date of Loss: 31/05/2022 Nature of Claim: TP Claim No: MCV2022D0003053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP3146S**
 Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: L15B4035588
 Reg. Date: 31/05/2017 (Man. Year: 2016) Chassis No: RU11115586
 Colour: White Odometer: 72691 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,318.04	4,691.20	626.84	11.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,020.00	1,150.00	53.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,488.04	5,711.20	1,776.84	23.73
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	7,488.04	4,550.00	2,938.04	39.24
+ GST 7.00/7.00% (S\$)	524.16	318.50	205.66	39.24
Nett Amount (S\$)	8,012.20	4,868.50	3,143.70	39.24
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,298.50		

INSPECTION

Date of Assignment: 03/06/2022
 Date Inspected: 13/06/2022 Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines)
 Blk 9006 #01-200 Tampines St 93
 Singapore
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jul 2022)

Parts: 144 HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP3146S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	927.50 FL	*801.20 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	36.00 FL	*36.00 FL
3	1		*FRONT BUMPER CENTER GRILLE	Serviceable	86.20 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	257.30 FL	*257.30 FL
5	1		*FRONT BUMPER REINFORCEMENT MOULDING	No such part	35.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GARNISH	Serviceable	212.70 FL	*- FL
7	1		*RADIATOR GRILLE BASE	Cracked	301.20 FL	*301.20 FL
8	1		*RADIATOR GRILLE OUTER	Cracked	202.90 FL	*202.90 FL
9	1		*RADIATOR GRILLE LOGO	Necessary	24.10 FL	*24.10 FL
10	2		*RADIATOR GRILLE CHROME MOULDING	Necessary	78.40 FL	*78.40 FL
11	2		*RADIATOR GRILLE SIDE BRACKET	Not Necessary	38.00 FL	*- FL
12	1		*RADIATOR GRILLE CENTER BRACKET	Not Necessary	42.10 FL	*- FL
13	1		*AMBIENT SENSOR	Not Necessary	48.80 FL	*- FL
14	2		*HEADLAMP	Holder Cracked	3,994.40 FL	*3,980.40 FL
15	2		*HEADLAMP LOWER BRACKET	Cracked	70.00 FL	*70.00 FL
16	1		*RADIATOR SUPPORT TOP GARNISH	Not Necessary	56.10 FL	*- FL
17	1		*BONNET LOCK	Not Necessary	80.60 FL	*- FL
18	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
19	1		*FRONT NUMBER PLATE	Scratched	45.00 FS	*40.00 FS
20	1		*SET RADIATOR SUPPORT TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,616.30	5,841.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,298.26	1,150.30
Total Parts (\$\$)	5,318.04	4,691.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	20.00
2	LABOUR /PANEL BEATING ,REPAIR BONNET AND SUPPORT PANEL	New	800.00	400.00
3	ANTI-RUST AND BODY SEALANT TO VACUUM ,REOIL AND REGAS AIR CON	New	120.00	0.00
4	SPRAY PAINTING 1)BUMPER 2)REINFORCEMENT 3) SUPPORT 4) BONNET 5)O/S FRT FENDER 6) N/S FRT FENDER	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,170.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >