

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22005555/UPA3Q2**Date:** 04/01/2023REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7220050993   |
| <b>Claimant Vehicle No :</b> | SLK2039B                             | <b>Insured Vehicle No :</b> | EV1686P      |
| Date of Loss:                | 10/06/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 6518141133SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLK2039B</b>                   | Engine No:  | R16B21601076      |
| Make & Model:               | HONDA CIVIC, 1.6 VTI CVT (A)      | Chassis No: | MRHFC5650GT000814 |
| Reg. Date:                  | 09/01/2017 (Man. Year: 2016)      | Odometer:   | 75626 km          |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1597 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55 R16    | Rear Tyre Size:  | 215/55 R16    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 6,414.80          | 1,514.08          | 4,900.72          | 76.40         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 1,880.00          | 1,050.00          | 830.00            | 44.15         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>8,294.80</b>   | <b>2,564.08</b>   | <b>5,730.72</b>   | <b>69.09</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,050.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 8,294.80          | 2,050.00          | 6,244.80          | 75.29         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 580.64            | 143.50            | 437.14            | 75.29         |
| <b>Nett Amount (S\$)</b>                        | <b>8,875.44</b>   | <b>2,193.50</b>   | <b>6,681.94</b>   | <b>75.29</b>  |
| <b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b> |                   | 300.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>2,495.50</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                         |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 13/06/2022 |                                                                                                         |
| Date Inspected:             | 13/06/2022 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                         |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition       | Repairer's | Amount     |
|-----|-----|----------|------------------------------------------|-----------------|------------|------------|
| 1   | 1   |          | *BONNET                                  | Not Necessary   | 822.10 F   | *- FL      |
| 2   | 1   |          | *SET BONNET INNER STICKER                | Not Necessary   | 60.00 F    | *- FL      |
| 3   | 1   |          | *FRONT BUMPER                            | Torn            | 945.20 F   | *579.90 FL |
| 4   | 1   |          | *FRONT BUMPER SIDE RETAINERS             | O/S Cracked     | 61.60 F    | *30.80 FL  |
| 5   | 1   |          | *FRONT BUMPER CENTRE GRILLE              | Not Necessary   | 89.20 F    | *- FL      |
| 6   | 1   |          | *FRONT BUMPER CENTRE TOP BEAM            | Not Necessary   | 165.20 F   | *- FL      |
| 7   | 1   |          | *FRONT BUMPER TOP RUBBER                 | Not Necessary   | 68.00 F    | *- FL      |
| 8   | 1   |          | *FRONT BUMPER BEAM                       | Repair          | 299.80 F   | *- FL      |
| 9   | 1   |          | *FRONT BUMPER GARNISH O/S                | Grazed          | 166.00 F   | *105.40 FL |
| 10  | 1   |          | *FRONT GRILLE                            | Not Necessary   | 325.30 F   | *- FL      |
| 11  | 1   |          | *FRONT GRILLE CHROME MOULDING            | Not Necessary   | 288.30 F   | *- FL      |
| 12  | 1   |          | *FRONT GRILLE H LOGO                     | Not Necessary   | 38.00 F    | *- FL      |
| 13  | 1   |          | *HEADLAMP O/S                            | Cracked         | 825.30 F   | *668.50 FL |
| 14  | 1   |          | *HEADLAMP TOP CHROME MOULDING O/S        | Not Necessary   | 108.00 F   | *- FL      |
| 15  | 1   |          | *FRONT SUPPORT PANEL                     | Repair          | 665.20 F   | *- FL      |
| 16  | 1   |          | *FRONT FENDER O/S                        | Repair          | 612.00 F   | *- FL      |
| 17  | 1   |          | *FRONT FENDER INNER SHIELD O/S           | Deformed / Torn | 245.80 F   | *182.50 FL |
| 18  | 1   |          | *FRONT FENDER LAMP O/S                   | Cracked         | 68.00 F    | *68.00 FL  |
| 19  | 1   |          | *WIPER WASHER TANK                       | Deformed        | 221.80 F   | *182.50 FL |
| 20  | 1   |          | *IMPACT SENSOR O/S                       | Serviceable     | 250.00 F   | *- FL      |
| 21  | 1   |          | *SET FRONT BUMPER CLIPS                  | Necessary       | 30.00 FS   | *30.00 FS  |
| 22  | 1   |          | *SET FRONT FENDER INNER SHIELD CLIPS O/S | Necessary       | 30.00 FS   | *30.00 FS  |
| 23  | 1   |          | *SET BONNET INSULATOR CLIPS              | Not Necessary   | 30.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                 |                 |
|---------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>6,414.80</b> | <b>1,877.60</b> |
| <b>- List Item Discount on L Items 0.00/20.00% (\$)</b> | 0.00            | 363.52          |
| <b>Total Parts (\$)</b>                                 | <b>6,414.80</b> | <b>1,514.08</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                               | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                           |          |                 |                 |
| 1                              | TO CHECK WIRING                           | New      | 50.00           | 20.00           |
| 2                              | TO SPRAY RUST PROOFING                    | New      | 60.00           | 20.00           |
| 3                              | TO REFILL AIR CON GAS                     | New      | 120.00          | 0.00            |
| 4                              | TO RESET & REPROGRAMME SYSTEM             | New      | 150.00          | 60.00           |
| 5                              | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 600.00          | 450.00          |
| 6                              | TO PUTTY & SPRAY PAINTING                 | New      | 900.00          | 500.00          |
| <b>Gross Labour Cost (S\$)</b> |                                           |          | <b>1,880.00</b> | <b>1,050.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >