



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No : 6143472L
 Make/Model : Y/DYNA
 CHASSIS NO : 17FUF347503010157

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	☒

WORK SHOP REPAIRER ESTIMATE

Date: 13.6.22

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARK

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARK
1	1	LH FRONT DOOR Dented ✓		\$ -	\$ 1461.35	✓
2	1	LH FRONT DOOR TOP MOLDING ^{new} X.		\$ -	\$ 74.10	X
3	1	LH FRONT DOOR OUTER HANDLE Lt ✓		\$ -	\$ 210.10	✓
4	2	LH FRONT DOOR HINGE TOP/BOTTOM Bnd ✓		\$ 73.20	\$ 146.40	✓
5	1	LH FRONT DOOR LOCK Dented ✓		\$ -	\$ 509.40	303
6	1	LH FRONT DOOR WEATHER STRIP ^{new} X		\$ -	\$ 326.40	X
7	1	LH FRONT DOOR INNER TRIM BOARD Bnd ✓		\$ -	\$ 606.20	✓
8	1	LH FRONT DOOR INNER BOARD CLIP ^{new} SN ✓		\$ -	\$ 55.00	✓
9	1	LH FRONT CONNER PANEL Dented ✓		\$ -	\$ 258.10	✓
10	1	LH FRONT LOWER STRIP PANEL Lt ✓		\$ -	\$ 110.35	✓
11	1	LH FRONT SIDE MIRROR RACK ^{new} X		\$ -	\$ 259.10	X
12	1	LH FRONT SIDE MIRROR RACK BARNISH ^{new} X.		\$ -	\$ 157.20	X
13	1	LH FRONT HEAD LAMP Bnd ✓		\$ -	\$ 690.40	✓
14	1	FRONT BUMPER Dented ✓		\$ -	\$ 461.30	✓
15	1	LH FRONT METAL RIM Lt ✓		\$ -	\$ 400.15	250(SN)
16	1	LH FRONT SHOCK ABSORBER Bnd ✓		\$ -	\$ 110.20	✓
17	1	LH FRONT WHEEL BEARING Bnd ✓		\$ -	\$ 201.30	✓
18	2	LH FRONT WHEEL BEARING OIL SEAL Bnd ✓		\$ 65.10	\$ 130.20	✓
19	1	LH FRONT WHEEL BEARING HUB Bnd ✓		\$ -	\$ 210.10	✓
20	1	LH REAR CONNER PANEL. ^{new} X.		\$ -	\$ 1745.10	X

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

812245



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

AXLE

EXLER

Vehicle No : 643472L
 Make/Model : 7/24NA.
 CHASSIS NO : _____

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	☒

WORK SHOP REPAIRER ESTIMATE

Date: 13.6.22

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARK

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARK
1	1	RH FRONT METAL RIM <i>metal</i> ✓		\$ -	\$ 400.15	250(SN)
2	1	RH FRONT WHEEL BEARING <i>Per d</i> ✓		\$ -	\$ 201.30	✓
3	1	RH FRONT WHEEL BEARING HUB <i>Per d</i> ✓		\$ -	\$ 210.10	✓
4	1	RH FRONT SHOCK ABSORBER <i>Best</i> ✓		\$ -	\$ 110.20	✓
5	1	RH FRONT STEERING BOX RACK LINK <i>Best</i> ✓		\$ -	\$ 240.30	✓
6	2	RH REAR METAL RIM <i>INNER/OUTER</i> <i>Best</i> ✓		\$ 310.30	\$ 620.60	500(SN)
7	1	RH REAR WHEEL BEARING <i>Per d</i> ✓		\$ -	\$ 201.30	✓
8	1	RH REAR WHEEL EXTER SHAFT <i>Per d</i> ✓		\$ -	\$ 606.10	✓
9	1	REAR EXTER SHAFT BOX. <i>NE NEI</i>		\$ -	\$ 4030.35	X
10	2	RH REAR WHEEL OIL SEAL. <i>Per</i> ✓		\$ 65.10	\$ 130.20	✓
11	1	LH SIDE GATE <i>Per</i>		\$ -	\$ 1968.90	X
12	1	FRONT CROSS MEMBER <i>Best</i> ✓		\$ -	\$ 1654.89	✓
13		Rear Axle Carrier. <i>Per d</i> ✓		\$ -	\$ 4010.35	✓
14		Rear Brake Drum <i>Per m</i> X.		\$ -	\$ 401.10	X
15		12378.74		\$ -	\$ -	
16		Len 25% 9284.05		\$ -	\$ -	
17		SN: 1000		\$ -	\$ -	
18				\$ -	\$ -	
19				\$ -	\$ -	
20				\$ -	\$ -	

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

14785.84



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No : 8443472L
 Make/Model : Y/ DYNA.
 CHASSIS NO : _____

INDEPENDENT SURVEYOR	
DIRECT SETTLEMENT	

WORK SHOP REPAIRER ESTIMATE

Date: _____

Estimate cost of repair to the above mentioned

MARKING UNIT \$ AMOUNT (\$\$) REMARK

NO.	QTY	List Items	MARKING	UNIT \$	AMOUNT (\$\$)	REMARK
1		PANEL BEAT		\$ -	\$ 2000.	1100
2				\$ -	\$ -	
3		SPRAY PAINT		\$ -	\$ 1800.	1200
4				\$ -	\$ -	
5		TO REMOVE/REPAIR L4 FRONT UNDERCARRIAGE		\$ -	\$ 250.	220
6				\$ -	\$ -	260
7		TO REMOVE/REPAIR FRONT WHEEL HUB		\$ -	\$ 350.	280
8				\$ -	\$ -	
9		TO REMOVE/REPAIR REAR WHEEL HUB		\$ -	\$ 450.	350
10		GEAR BOX.		\$ -	\$ -	
11				\$ -	\$ -	
12		GEAR BOX OIL.		\$ -	\$ 120.	100
13				\$ -	\$ -	
14		WHEEL ALIGNMENT.		\$ -	\$ 80.	✓
15				\$ -	\$ -	
16		RUST PROOF		\$ -	\$ 150.	120
17				\$ -	\$ -	
18				\$ -	\$ -	
19				\$ -	\$ -	
20				\$ -	\$ -	

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

EMAIL ADD: play damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

08 Days.

28108.29

CONTACT:

total 13754.05

r/s: 11K 08 Days

Scanned with CamScanner