



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: GARNET LOW			Ref: CS/ASM22005559/Ance2 Date: 19/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 1328T	Veh. Inspected	GY 3472L	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M043DP	Excess (\$)	0.00	
Assign From	GARNET LOW	Assign Date	13/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JTFUF34Y503010157	Colour	SILVER	
Odometer	653364 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C	TOURADOR	6 mm	
L/H Front Tyre	185 R14C	TOURADOR	6 mm	
R/H Rear Tyre	165 R13C	TOURADOR	6 mm	
L/H Rear Tyre	165 R13C	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2022	Inspection Date	13/06/2022	
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	