

ASS. REC. BY:

REF:

TU  
GRB / 1-22005569/Ke

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: @124K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: Smm 5243K Yr Regn: 07, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A) Wagon  
Make: Toy Noah c.c 1797

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 224509 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: ZWR80 . 0387259

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Farroad

Front Rear  
R/Bal. 9 mm R/Bal. 9 mm  
L/Bal. 9 mm L/Bal. 9 mm  
D.O.A. 1/6/22 D.O.I. 7/6/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/6 / 1 Pm @ 3000 Carbu

Date/Time, File Pass to?

: Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

\$ - RS. SI

Fuel

Others

TOTAL

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541  
Tel : 64817221

*Not Authorized  
01 Rep @ 3100h  
Resurvey After Paint  
4 days*

Fax : 64816131

L H Car Rental Pte Ltd  
Blk 5038 #01-405  
Ang Mo Kio Industrial Pk 2  
Singapore 569541

Vehicle No : SMM 5243 K  
Make/Model : Toyota Noah  
Year : 2019

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear tail-gate <i>1712</i>	<i>By</i> \$1,750.80	—
1 pc	Rear tail-gate glass moulding	<i>M</i> \$185.70	—
1 pc	Rear tail-gate emblem " Hybrid "	<i>M</i> \$65.10	—
1 pc	Rear tail-gate inner lock	<i>R</i> \$285.60	X
1 pc	Rear boot rubber	<i>R</i> \$265.30	X
1 pc	Rear bumper <i>with colour code 1180</i>	<i>By</i> \$1,255.90	—
2 pcs	Rear bumper side retainer	\$155.70 <i>R</i>	\$311.40 X
			\$4,119.80
		Less 25 %	\$1,029.95
			\$3,089.85

## S Nett

1 pc	Rear tail-gate glass sealant	<i>M</i> \$40.00	—
20 pcs	Rear bumper clip	\$2.00 <i>M</i>	\$40.00 —
1 pc	Rear reverse sensor	<i>NA / Short</i>	\$200.00 —
			\$280.00

## Labour charges

Remove/renew the above parts including knocking, welding & cutting.	\$600.00	<i>50%</i>
To putty and spray paint	\$600.00	<i>50%</i>
Check and reconnect wiring	\$30.00	<i>20%</i>
To respray anti-rust proofing treatment	\$60.00	<i>30%</i>
Remove/refit rear windscreen to facilitate repair	\$120.00	✓
Remove/refit rear tail-gate mechanism to new door	\$100.00	<i>60%</i>
	<u>\$4,879.85</u>	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: