

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005571/KPA3Q2**Date:** 17/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210088468
Claimant Vehicle No :	SHF503P	Insured Vehicle No :	SGK1008G
Date of Loss:	04/06/2022	Nature of Claim:	TP
		Claim No:	7500416226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF503P		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H43156
Reg. Date:	15/01/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU803093346
Colour:	Metallic Pearl White/Red	Odometer:	122360 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Lanvigaton 6 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Lanvigaton 6 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,127.17	3,749.17	3,378.00	47.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,670.00	890.00	7,780.00	89.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,797.17	4,639.17	11,158.00	70.63
+ GST 7.00/7.00% (\$\$)	1,105.80	324.74	781.06	70.63
Nett Amount (\$\$)	16,902.97	4,963.91	11,939.06	70.63
+ Loss of Use (4.5 x S\$50.00/day) (\$\$)		225.00		
+ Car Rental (4.5 x S\$96.30/day) (\$\$)		433.35		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,629.71		

INSPECTION

Date of Assignment:	07/06/2022		
Date Inspected:	07/06/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

11/17/22, 4:00 PM

Adjuster Report

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled / Cracked	521.00 FL	*521.00 FL
2	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	110.50 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
5	1		*SUPPORT FRONT BUMPER SIDE,RH	Distorted	80.10 FL	*80.10 FL
6	1		*COVER ,FRONT BUMPER HOLE RH	Missing	30.20 FL	*30.20 FL
7	1		*MOULDING FRONT BUMPER SIDE ,RH	Cracked	95.60 FL	*95.60 FL
8	1		*UNIT ASSY ,HEADLAMP ,RH	Mtg Broken	2,637.60 FL	*2,637.60 FL
9	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
10	1		*LINER ,FRONT FENDER ,RH	Distorted	202.50 FL	*202.50 FL
11	1		*EMBLEM ,SIDE PANEL ,RH	Necessary	54.60 FL	*54.60 FL
12	1		*HOOD SUB-ASSY	Repair	983.10 FL	*- FL
13	1		*SUPPORT ASSY, HOOD	Repair	44.20 FL	*- FL
14	1		*HINGE ASSY ,HOOD, LH	Repair	58.90 FL	*- FL
15	1		*HINGE ASSY ,HOOD, RH	Repair	58.90 FL	*- FL
16	1		*COVER SUB-ASSY ,FRONT PILLAR ,UPR RH	Missing	100.40 FL	*100.40 FL
17	1		*HUB CAP	Serviceable	211.50 FL	*- FL
18	1		*RIM	Serviceable	1,900.10 FL	*- FL
19	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*60.00 FS
20	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
21	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
22	1		*SET BONNET INSULATOR CLIP	Not Necessary	70.00 FS	*- FS
23	1		*JAR ASSY WINDSHIELD WASHER	Dented	219.10 FL	*219.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,397.90	4,978.90
- List Item Discount on L Items 25.00/25.00% (\$)	2,270.73	1,229.73
Total Parts (\$)	7,127.17	3,749.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
5	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	480.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIB BENCH TO FACILITATE REPAIR	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	220.00	0.00
14	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
15	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			8,670.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >