

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG22005576/UNCE2

Date: 20/07/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001960871		
Claimant Vehicle No :	SLH7231U	Insured Vehicle No :	SLM9749D		
Date of Loss:	11/06/2022	Nature of Claim:	TP	Claim No:	276502

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH7231U	Engine No:	4A92CL7290
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Chassis No:	JMYSRCY1AGU005926
Reg. Date:	17/11/2016 (Man. Year: 2016)	Odometer:	261159 km
Colour:	Grey		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,455.00	2,725.90	3,729.10	57.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,300.00	1,240.00	48.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,995.00	4,025.90	4,969.10	55.24
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	8,995.00	3,200.00	5,795.00	64.42
+ GST 7.00/7.00% (S\$)	629.65	224.00	405.65	64.42
Nett Amount (S\$)	9,624.65	3,424.00	6,200.65	64.42

INSPECTION

Date of Assignment:	15/06/2022		
Date Inspected:	13/06/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2022)		
Parts:	143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH7231U)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,200.00 F	*865.00 FL
2	1		*REAR BUMPER REFLECTORS	N/S Cracked	136.00 F	*45.00 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	38.00 F	*- FL
4	2		*REAR BUMPER SIDE RETAINERS	Necessary	120.00 F	*76.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	318.00 F	*234.00 FL
6	1		*REAR BUMPER TOP BEAM	Bent	122.00 F	*122.00 FL
7	1		*REAR END PANEL	Repair	545.00 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Serviceable	168.00 F	*- FL
9	1		*TAILLAMP LED N/S	Cracked	885.00 F	*885.00 FL
10	1		*REAR FENDER INNER TRIM N/S	Torn	282.00 F	*282.00 FL
11	1		*REAR ANTENNA SENSOR	Cracked	188.00 F	*142.00 FL
12	1		*REAR BUZZLE SENSOR	Not Necessary	152.00 F	*- FL
13	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	316.00 F	*- FL
14	1		*BOOTLID	Not Necessary	1,122.00 F	*- FL
15	1		*BOOTLID WEATHERSTRIP	Not Necessary	238.00 F	*- FL
16	1		*SET REAR LICENCE PLATE LAMP	Not Necessary	145.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
18	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
19	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
21	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
Sub Total (\$\$)						6,455.00 2,991.00
- List Item Discount on L Items 0.00/10.00% (\$\$)						0.00 265.10
Total Parts (\$\$)						6,455.00 2,725.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
5	TO SPRAY RUST PROOFING	New	60.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	550.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,540.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >