

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005578/TNY3Q2
Date: 18/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNW00108812203	
Claimant Vehicle No : SML6932D	Insured Vehicle No : SME9735Z	
Date of Loss: 07/06/2022	Nature of Claim: TP	Claim No: SNM22D204026/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML6932D		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB7102882
Reg. Date:	30/05/2019 (Man. Year: 2018)	Chassis No:	GP72002113
Colour:	White	Odometer:	281924 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,149.16	2,435.36	3,713.80	60.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,540.00	2,060.00	57.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,749.16	3,975.36	5,773.80	59.22
Approved Total (Overridden) (S\$)		3,200.00		
	9,749.16	3,200.00	6,549.16	67.18
+ GST 7.00/7.00% (S\$)	682.44	224.00	458.44	67.18
Nett Amount (S\$)	10,431.60	3,424.00	7,007.60	67.18

INSPECTION

Date of Assignment:	13/06/2022	
Date Inspected:	14/06/2022	Inspected At:
Estimated Period of Repair:	5.0 days	9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840 Repairer:AP Automotive Services Pte Ltd

11/18/22, 11:35 AM

Adjuster Report

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Nov 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML6932D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,025.00 FL	*1,025.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	158.75 FL	*120.00 FL
3	1		*REAR TAILGATE LOGO HONDA	Necessary	98.75 FL	*60.00 FL
4	1		*REAR TAILGATE LOGO SHUTTLE	Necessary	84.88 FL	*50.00 FL
5	1		*REAR TAILGATE LOGO HYBRID	Necessary	106.38 FL	*55.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Cut	187.50 FL	*168.20 FL
7	1		*REAR BUMPER	Deformed	1,437.50 FL	*936.00 FL
8	2		*REAR BUMPER REFLECTOR	Not Necessary	177.50 FL	*- FL
9	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	281.00 FL	*- FL
10	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	107.50 FL	*- FL
11	1		*REAR BUMPER RETAINER	N/S Not Necessary/O/S Deformed	200.00 FL	*100.00 FL
12	2		*REAR BUMPER BRACKET	Not Necessary	262.50 FL	*- FL
13	1		*REAR BUMPER UNDER COVER	Not Necessary	590.00 FL	*- FL
14	1		*END PANEL	Repair	615.83 FL	*- FL
15	1		*END PANEL TOP GARNISH	Deformed	167.50 FL	*167.50 FL
16	1		*REAR SMART LOCK ANTENNA	Not Necessary	243.75 FL	*- FL
17	1		*REAR BUZZER	Not Necessary	182.50 FL	*- FL
18	1		*NUMBER PLATE	Not Necessary	55.00 FS	*- FS
19	1		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
20	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*50.00 FS
21	1		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
22	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
23	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*END PANEL TOP GARNISH CLIP	Necessary	80.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,741.84	2,971.70
- List Item Discount on L Items 10.00/20.00% (\$\$)	592.68	536.34
Total Parts (\$\$)	6,149.16	2,435.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
3	REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
4	CHECK WIRING AND TAIL LAMP FUNCTIONS	New	100.00	30.00
5	WATER LEAK CHECK	New	100.00	0.00
6	REMOVE AND REFIT UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	60.00
7	REMOVE AND REFIT REAR TAILGATE MECHANISM	New	200.00	60.00
8	REMOVE AND REFIX REVERSE SENSOR AND CHECK FUNCTIONS	New	80.00	30.00
9	APPLY ANTI RUST	New	120.00	40.00
Gross Labour Cost (\$\$)			3,600.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >