

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005580/TNY3E2**Date:** 13/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00088332103

**Claimant Vehicle
No :** FBN6192S**Insured Vehicle
No :** GX7572K

Date of Loss: 04/06/2022

Nature of Claim: TP

Claim
No: SNM22D204039/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBN6192S**

Make & Model: YAMAHA CZD300A / XMAX300, 292cc

Engine No: H336E0043292

Reg. Date: 10/11/2018 (Man. Year: 2018)

Chassis No: MH3SH0849KK005070

Colour: Silver

Odometer: 0 km

Engine Capacity: 292 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R15

Rear Tyre Size: 150/70 R14

Front Left Side: MITAS 5 mm

Rear Left Side: MITAS 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,420.00	2,640.00	4,780.00	64.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	530.00	420.00	44.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,370.00	3,170.00	5,200.00	62.13
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	8,370.00	2,500.00	5,870.00	70.13
+ GST 8.00/8.00% (S\$)	669.60	200.00	469.60	70.13
Nett Amount (S\$)	9,039.60	2,700.00	6,339.60	70.13

INSPECTION

Date of Assignment: 02/12/2022

Date Inspected: 14/06/2022 Inspected At:

Erzat Lee Motor Trading Pte Ltd (HQ)
Synergy@KB 25, Kaki Bukit Road 4 #03-37
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Mar 2023)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN6192S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORK (LOCAL REPAIR) }	Shifted	550.00 FS	*150.00 FS
2	1		*T-FORK (LOCAL REPAIR) }		350.00 FS	*- FS
3	1		*WHEEL SHAFT (FRONT)	Bent	55.00 F	*55.00 FL
4	1		*FRONT RIM (LOCAL REPAIR)	Cut	250.00 FS	*50.00 FS
5	1		*DISC BRAKE	Dented	135.00 F	*135.00 FL
6	1		*HEADLIGHT COVER	Cut	350.00 F	*200.00 FL
7	1		*HEADLIGHT INNER COVER	Not Necessary	200.00 F	*- FL
8	1		*SET MIRROR	Cut	50.00 F	*50.00 FL
9	1		*WINDSHIELD	Not Necessary	120.00 F	*- FL
10	1		*WINDSHIELD BRACKET	Not Necessary	80.00 F	*- FL
11	1		*HEADLIGHT	Cut	650.00 F	*520.00 FL
12	1		*WINDSHIELD BRACKET COVER	Not Necessary	80.00 F	*- FL
13	1		*FRONT RIGHT SPOTLIGHT	Cut	55.00 F	*55.00 FL
14	1		*FRONT RIGHT FAIRING	Cut	180.00 F	*180.00 FL
15	1		*FRONT RIGHT INNER PANEL	Cut	150.00 F	*150.00 FL
16	1		*HANDLE BAR	Bent	250.00 F	*150.00 FL
17	1		*BALANCER (LEFT & RIGHT)	N/S Not Necessary / O/S Cut	80.00 F	*40.00 FL
18	1		*FRONT LOWER SPOTLIGHT (RIGHT)	Cut	55.00 F	*55.00 FL
19	1		*FRONT LOWER SPOTLIGHT BRACKET (RIGHT)	Bent	80.00 F	*80.00 FL
20	1		*RIGHT FOOTPAD	Cut	55.00 F	*55.00 FL
21	1		*COVER SIDE RH	Cut	180.00 F	*100.00 FL
22	1		*REAR FAIRING (LEFT & RIGHT)	O/S Cut	400.00 F	*200.00 FL
23	1		*EXHAUST COVER	Cut	120.00 F	*120.00 FL
24	1		*FOOTPAD UNDER COVER (RIGHT)	Cut	1,200.00 F	*260.00 FL
25	1		*REAR ABSORBER (LEFT & RIGHT)	Not Necessary	450.00 F	*- FL
26	1		*REAR LIGHT COVER	Not Necessary	450.00 F	*- FL
27	1		*BOX BRACKET	Dented	180.00 F	*180.00 FL
28	1		*PLATE NUMBER	Bent	15.00 F	*15.00 FL
29	1		*REAR EXHAUST (LOCAL REPAIR)	Scratched	500.00 FS	*100.00 FS
30	1		*REAR RIGHT INNER PANEL	Not Necessary	150.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,420.00	2,900.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	260.00
Total Parts (\$\$)	7,420.00	2,640.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	500.00	300.00
2	WIRING	New	50.00	30.00
3	SPRAY PAINTING	New	400.00	200.00
Gross Labour Cost (\$)			950.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >