

CS/QT.122005580/Tay 3

) Photos

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 9-Jun-22

Estimate no.

1129

Plate No. FBN 6192S

Model. XMAX

Tan Guan 97495749
inv 14/6/22 @ 3pm
4/5 hrs for repair 4 days
Tan Guan 97495749

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK	\$ 550.00	x 7 shifted	
2	T-FORK	\$ 350.00	x 1 R 150 LR	
3	WHEEL SHAFT(FRONT)	\$ 55.00	? bt	
4	Front Rim	\$ 250	R 250 SN 150 LR	
5	DISC BRAKE	\$ 135.00	? dt	
6	HEADLIGHT COVER	\$ 350.00	cut 200	
7	HEADLIGHT INNER COVER	\$ 200.00	x nn	
8	MIRROR SET	\$ 50.00	cut	
9	WINDSHIELD	\$ 120.00	x nn	
10	WINDSHIELD BRACKET	\$ 80.00	x nn	
11	HEADLIGHT	\$ 650.00	cut 520	
12	WINDSHIELD BRACKET COVER	\$ 80.00	x nn	
13	FRONTRIGHT SPOTLIGHT	\$ 55.00	cut	
14	FRONT RIGHT FAIRING	\$ 180.00	cut	
15	FRONT RIGHT INNER PANEL	\$ 150.00	cut	
16	HANDLE BAR	\$ 250.00	? bt 150	
17	BALANCER (LEFT & RIGHT)	\$ 80.00	cut 40	
18	FRONT LOWER SPOTLIGHT (RIGHT)	\$ 55.00	x cut	
19	FRONT LOWER SPOTLIGHT BRACKET (RIGHT)	\$ 80.00	bt	
20	RIGHT FOOTPAD	\$ 55.00	cut	
21	COVER SIDE (LEFT) RH	\$ 180.00	RH cut 100	
22	REAR FAIRING (LEFT & RIGHT) RH	\$ 400.00	cut 200	
23	EXHAUST COVER	\$ 120.00	cut	
24	REAR RIGHT INNER PANEL	\$ 150.00	x nn	
25	FOOTPAD UNDER COVER (RIGHT)	\$ 1,200.00	cut 260	
26	REAR ABDOSBER(LEFT & RIGHT)	\$ 450.00	x nn	
27	REAR LIGHT COVER	\$ 450.00	x nn	
28	BOX BRACKET	\$ 180.00	dt	
29	PLATE NUMBER	\$ 15.00	bt	

30

Rear Exhaust ... ser. 500 X R SN 100 LR

Labour - \$ 500 300
Wiring - \$ 50 30
Spray painting - \$ 400 200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

2600
10% - 2340
SN - 350
530

3220
265 \$ 2500
4 days

*Estimate given are base on visible damages ONLY before dismantling of the vehicle surveyed and is subject to final approval from Insurance Company

This is computer generated no signature is required.

Acknowledged by Repairer