

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005607/TPA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900231926-01
Claimant Vehicle No : SMQ241C **Insured Vehicle No :** SMP8566T
 Date of Loss: 11/06/2022 Nature of Claim: TP Claim No: 0853591411SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ241C**
 Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC34871
 Reg. Date: 25/10/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V9LA007106
 Colour: White Odometer: 24964 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,693.00	1,342.40	10,350.60	88.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,242.00	1,610.00	56.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,545.00	2,584.40	11,960.60	82.23
+ GST 8.00/8.00% (S\$)	1,163.60	206.75	956.85	82.23
Nett Amount (S\$)	15,708.60	2,791.15	12,917.45	82.23
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,943.15		

INSPECTION

Date of Assignment: 16/06/2022
 Date Inspected: 16/06/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,433.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LH	Not Necessary	318.00 FS	*- FS
4	1		*FRONT BUMPER TRIM COVER -LH	Not Necessary	182.00 FS	*- FS
5	1		*RADIATOR GRILLE	Cut	1,578.00 FS	*1,262.40 FS
6	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	210.00 FS	*- FS
7	1		*AIR COND STICKER	Necessary	9.00 FS	*7.20 FS
8	1		*CAUTION STICKER	Necessary	16.00 FS	*12.80 FS
9	1		*FRONT BUMPER GUIDE GRILLE -LH	Not Necessary	210.00 FS	*- FS
10	1		*HEADLIGHT -LH	Not Necessary	5,879.00 FS	*- FS
11	1		*RADIATOR AIR GUIDE -LH	Not Necessary	28.00 FS	*- FS
12	1		*RADIATOR AIR GUIDE -UPPER CENTER	Not Necessary	14.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
14	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
15	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,693.00	1,342.40
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	550.00
4	TO RESPRAY FRONT BUMPER	New	900.00	500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,852.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >